Forem 0 221		N. M. O.		JPY -		40	
Form 9–331 (Máy 1963)		ITED STAT		SUBMIT IN 1 (Other instruction	AICATE*	Budget i	Bureau No. 42
		MENT OF THE		K verse side)		5. LEASE DESIGNAT	
<u> </u>		EOLOGICAL SL	JRVEY			NM 056037	
SUN	DRY NOT	CES AND REI	PORTS O	N WELLS		6. IF INDIAN, ALLO	TTEE OR TRIB
(Do not use this	form for propos Use "APPLICA	als to drill or to deep TION FOR PERMIT—	en or plug bac	k to a different reserves	voir.		•;
1.						7. UNIT AGREEMEN	T NAVE
WELL CAS WELL CAS OTHER Water Injection							
2. NAME OF OPERATOR						8. FARM OR LEASE	NAME
Tenneco O	il Company					SW Henshaw	Premier
3. ADDRESS OF OPERATOR		· · · · · · · · · · · · · · · · · · ·				9. WELL NO.	
Box 1031, Midland, Texas 79701						1 - 6	•
 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) 						10. FIELD AND POO	L, OR WILDCA
At surface					Henshaw West (Grayb		
<i>.</i>						11. SEC., T., R., M., SURVEY OR	OR BLE, AND REA
660 FIIL & 66	O' FWL						
14. PERMIT NO.	· · · · · · · · · · · · · · · · · · ·	15. ELEVATIONS (Show	w whether DF	G. G. etc.)		Sec 17, T-1 12. COUNTY OF PAR	
				·, ···, ·····;			NM
•••			4 GR		· · · ·	Eddy	I INIM
16.	Check Ap	propriate Box To I	ndicate Nat	ure of Notice, Re	port, or C	Other Data	
N	OTICE OF INTEN:	TION TO:	1		SUBSEQU	JENT REPORT OF:	
TEST WATER SHUT-OF	'F P	TLL OR ALTER CASING		WATER SHUT-OFF		REPAIRI	
FRACTURE TREAT		ULTIPLE COMPLETE		FRACTURE TREAT		-	G CASING
SHOOT OR ACIDIZE		BANDON*		SHOOTING OR ACI		ABANDON	
REPAIR WELL	c	HANGE PLANS				Comp as WI	7
(Other)				(NOTE: Rep	port results	of multiple complet letion Report and Log	ion on Well
1. Cleaned o 2. Ran GR De 3. Ran 4 1/2	ut out hoinsity log " 10.5#	le to origina from 2333 ba J-55 Csg to	1 TD of 2 ck to sur 2833 and	etails, and give perti s and measured and 2783' and dri face Cemented W/20	lled ne	ew hole to 28	33 ¹ .
1. Cleaned o 2. Ran GR De 3. Ran 4 1/2 4. Ran 2 3/8	ut out ho: nsity log " l0.5# " injectio	le to origina from 2833 ba	l TD of 2 ck to sur 2833 and h packer	etails, and give perti s and measured and 2783' and dri face Cemented W/20	lled ne	ew hole to 28	33 ¹ .
 Cleaned o Ran GR De Ran 4 1/2 Ran 2 3/8 Will begi 	ut out ho nsity log " 10.5# " injection n injection	le to origina from 2333 ba J-55 Csg to on tubing wit on around 8-1	l TD of 2 ck to sur 2833 and h packer -69 3 8, 39, 4	Petails, and give pertises and measured and Person of the second	lled ne 00 sx c 49,50	whole to 28 alss C cemen	33 ¹ •
 Cleaned o Ran GR De Ran 4 1/2 Ran 2 3/8 Will begi 	ut out ho nsity log " 10.5# " injection n injection	le to origina from 2333 ba J-55 Csg to on tubing wit on around 8-1	l TD of 2 ck to sur 2833 and h packer -69 3 8, 39, 4	etails, and give pertises and measured and erion of the set of the	lled ne (49, 50)	whole to 28 alss C cemen	33 ¹ •
1. Cleaned o 2. Ran GR De 3. Ran 4 1/2 4. Ran 2 3/3 5. Will begi	ut out hoi nsity log " 10.5# " injection n injection the fall	le to origina from 2333 ba J-55 Csg to on tubing wit on around 8-1 with 2737 59	l TD of 2 ck to sur 2833 and h packer -69 3 8, 39, 4	etails, and give pertises and measured and erion of the set of the	lled ne (49, 50)	whole to 28 alss C cemen	33 ¹ •
1. Cleaned o 2. Ran GR De 3. Ran 4 1/2 4. Ran 2 3/3 5. Will begi	ut out hoi nsity log " 10.5# " injection n injection the fall	le to origina from 2333 ba J-55 Csg to on tubing wit on around 8-1	l TD of 2 ck to sur 2833 and h packer -69 3 8, 39, 4	etails, and give pertises and measured and 2783' and dri oface Cemented W/20 set at 2676' 40, 44, 48, 4 63, 64, 65	lled ne 00 sx c 49, 30, 66, 6	whole to 28 alss C cemen 57, 53, 55 7468	33 ¹ •
1. Cleaned o 2. Ran GR De 3. Ran 4 1/2 4. Ran 2 3/3 5. Will begi	ut out ho: nsity log " 10.5# " injection n injection the fall RECE	le to origina from 2333 ba J-55 Csg to on tubing wit on around 8-1 for around 8-1 for around 8-1	l TD of 2 ck to sur 2833 and h packer -69 3 8, 39, 4	etails, and give pertises and measured and 2783' and dri face Cemented W/20 set at 2676' 49, 44, 48, 4 63, 64, 65	lled ne 00 sx c 49, 50, 64, 6 ECEL	whole to 28 ealss C cemen 57, 52, 555 7669	33 ¹ •
1. Cleaned o 2. Ran GR De 3. Ran 4 1/2 4. Ran 2 3/3 5. Will begi	ut out ho: nsity log " 10.5# " injection n injection the fall RECE	le to origina from 2333 ba J-55 Csg to on tubing wit on around 8-1 for around 8-1 for around 8-1	l TD of 2 ck to sur 2833 and h packer -69 3 8, 39, 4	etails, and give pertises and measured and 2783' and dri face Cemented W/20 set at 2676' 49, 44, 48, 4 63, 64, 65	lled ne 00 sx c 49, 50, 64, 6 ECEL	whole to 28 ealss C cemen 57, 52, 555 7669	33 ¹ •
1. Cleaned o 2. Ran GR De 3. Ran 4 1/2 4. Ran 2 3/3 5. Will begi	ut out ho: nsity log " 10.5# " injection n injection the fall RECE	le to origina from 2333 ba J-55 Csg to on tubing wit on around 8-1 with 2737 59	l TD of 2 ck to sur 2833 and h packer -69 3 8, 39, 4	etails, and give pertises and measured and 2783' and dri face Cemented W/20 set at 2676' 49, 44, 48, 4 63, 64, 65	lled ne 00 sx c 49, 50, 64, 6 ECEL	whole to 28 ealss C cemen 57, 52, 555 7669	33 ¹ •
1. Cleaned o 2. Ran GR De 3. Ran 4 1/2 4. Ran 2 3/3 5. Will begi	ut out ho: nsity log " 10.5# " injection n injection AUG 5 AUG 5	le to origina from 2333 ba J-55 Csg to on tubing wit on around 8-1 for around 8-1	l TD of 2 ck to sur 2833 and h packer -69 3 8, 39, 4	etails, and give pertises and measured and 2783' and dri face Cemented W/20 set at 2676' 49, 44, 48, 4 63, 64, 65	lled ne 00 sx c 49, 50, 64, 6 ECEL	whole to 28 ealss C cemen 57, 52, 555 7669	33 ¹ •
1. Cleaned o 2. Ran GR De 3. Ran 4 1/2 4. Ran 2 3/3 5. Will begi	ut out ho: nsity log " 10.5# " injection n injection AUG 5 AUG 5	le to origina from 2333 ba J-55 Csg to on tubing wit on around 8-1 for around 8-1 for around 8-1	l TD of 2 ck to sur 2833 and h packer -69 3 8, 39, 4	etails, and give pertises and measured and 2783' and dri face Cemented W/20 set at 2676' 49, 44, 48, 4 63, 64, 65	lled ne 00 sx c 49, 50, 64, 6 ECEL	whole to 28 ealss C cemen 57, 52, 555 7669	33 ¹ •
1. Cleaned o 2. Ran GR De 3. Ran 4 1/2 4. Ran 2 3/3 5. Will begi	ut out ho: nsity log " 10.5# " injection n injection AUG 5 AUG 5	le to origina from 2333 ba J-55 Csg to on tubing wit on around 8-1 for around 8-1	l TD of 2 ck to sur 2833 and h packer -69 3 8, 39, 4	etails, and give pertises and measured and 2783' and dri face Cemented W/20 set at 2676' 49, 44, 48, 4 63, 64, 65	lled ne 00 sx c 49, 50, 64, 6 ECEL	whole to 28 alss C cemen 57, 53, 55 7468	33 ¹ •
1. Cleaned o 2. Ran GR De 3. Ran 4 1/2 4. Ran 2 3/3 5. Will begi	ut out ho: nsity log " 10.5# " injection n injection AUG 5 AUG 5	le to origina from 2333 ba J-55 Csg to on tubing wit on around 8-1 for around 8-1	l TD of 2 ck to sur 2833 and h packer -69 3 8, 39, 4	etails, and give pertises and measured and 2783' and dri face Cemented W/20 set at 2676' 49, 44, 48, 4 63, 64, 65	lled ne 00 sx c 49, 50, 64, 6 ECEL	whole to 28 ealss C cemen 57, 52, 555 7669	33 ¹ •
1. Cleaned o 2. Ran GR De 3. Ran 4 1/2 4. Ran 2 3/3 5. Will begi	ut out ho: nsity log " 10.5# " injection n injection AUG 5 AUG 5	le to origina from 2333 ba J-55 Csg to on tubing wit on around 8-1 for around 8-1	l TD of 2 ck to sur 2833 and h packer -69 3 8, 39, 4	etails, and give pertises and measured and 2783' and dri face Cemented W/20 set at 2676' 49, 44, 48, 4 63, 64, 65	lled ne 00 sx c 49, 50, 64, 6 ECEL	whole to 28 ealss C cemen 57, 52, 555 7669	33 ¹ •
<pre>proposed work.)* 1. Cleaned o 2. Ran GR De 3. Ran 4 1/2 4. Ran 2 3/3 5. Will begi Ref Thole a </pre>	ut out ho: nsity log " 10.5# " injection n injection the fall RECE AUG 5	le to origina from 2333 ba J-55 Csg to on tubing wit on around 8-1 for around 8-1	l TD of 2 ck to sur 2833 and h packer -69 3 8, 39, 4	etails, and give pertises and measured and 2783' and dri face Cemented W/20 set at 2676' 49, 44, 48, 4 63, 64, 65	lled ne 00 sx c 49, 50, 64, 6 ECEL	whole to 28 ealss C cemen 57, 52, 555 7669	33 ¹ •
1. Cleaned o 2. Ran GR De 3. Ran 4 1/2 4. Ran 2 3/3 5. Will begi	ut out ho: nsity log " 10.5# " injection n injection the fall RECE AUG 5	le to origina from 2333 ba J-55 Csg to on tubing wit on around 8-1 for around 8-1	1 TD of 2 ck to sur 2833 and h packer -69 3 8 , 39 , 4 9, (27)	Petails, and give pertises and measured and performance of the set at 2676' and drives at 2676' and the set at 267	true vertice lled ne 00 sx c 49 sr o 64 6 ECE AUG S. GEOLU ARTESIA	whole to 28 alss C cemen Si, 52, 55 2668 NED A 1969 GICAL SUNNE DGICAL SUNNE NEW BEAD	331.
<pre>proposed work.)* 1. Cleaned o 2. Ran GR De 3. Ran 4 1/2 4. Ran 2 3/3 5. Will begi Ref Thole a </pre>	ut out ho: nsity log " 10.5# " injection n injection the fall RECE AUG 5	true and-correct	1 TD of 2 ck to sur 2833 and h packer -69 3 8 , 39 , 4 9, (27)	etails, and give pertises and measured and 2783' and dri face Cemented W/20 set at 2676' 49, 44, 48, 4 63, 64, 65	true vertice lled ne 00 sx c 49 sr o 64 6 ECE AUG S. GEOLU ARTESIA	whole to 28 alss C cemen Si, 52, 55 2668 NED A 1969 GICAL SUNNE DGICAL SUNNE NEW BEAD	33 ¹ •
<pre>I. Cleaned o 2. Ran GR De 3. Ran 4 1/2 4. Ran 2 3/3 5. Will begi Pay Thole a 18. I bereby certify that the SIGNED</pre>	ut out ho: nsity log " 10.5# " injection n injection the follow AUG 5 	true and-correct	1 TD of 2 ck to sur 2833 and h packer -69 3 8 , 39 , 4 9, (27)	Petails, and give pertises and measured and performance of the set at 2676' and drives at 2676' and the set at 267	true vertice lled ne 00 sx c 49 sr o 64 6 ECE AUG S. GEOLU ARTESIA	whole to 28 alss C cemen 57, 53, 55 7468 NED A 969 UGICAL SUNN NEW ELICE NEW	331.
<pre>I. Cleaned o 2. Ran GR De 3. Ran 4 1/2 4. Ran 2 3/3 5. Will begi Pay Thole a 18. I bereby certify that the SIGNED</pre>	ut out ho: nsity log " 10.5# " injection n injection the follow AUG 5 	true and-correct	1 TD of 2 ck to sur 2833 and h packer -69 3 8 , 39 , 6 9 3 9 , 6 9 3 9 , 6 9 3 9 , 6 9	Petails, and give pertises and measured and performance of the set at 2676' and drives at 2676' and the set at 267	true vertice lled ne 00 sx c 49 sr o 64 6 ECE AUG S. GEOLU ARTESIA	Whole to 28 alss C cemen Si, 52, 55 2468 NED A 1969 A 1969 JGICAL SUNVE DGICAL SUNVE DGICAL SUNVE DGICAL SUNVE	331.
<pre>I. Cleaned o 2. Ran GR De 3. Ran 4 1/2 4. Ran 2 3/3 5. Will begi Pay Thole a 18. I bereby certify that the SIGNED</pre>	ut out ho: nsity log " 10.5# " injection n injection the follow AUG 5 	true and-correct	1 TD of 2 ck to sur 2833 and h packer -69 3 8 , 39 , 4 9, (27)	Petails, and give pertises and measured and performance of the set at 2676' and drives at 2676' and the set at 267	true vertice lled ne 00 sx c 49 sr o 64 6 ECE AUG S. GEOLU ARTESIA	whole to 28 alss C cemen 57, 53, 55 7468 NED A 969 UGICAL SUNN NEW ELICE NEW	331.
<pre>I. Cleaned o 2. Ran GR De 3. Ran 4 1/2 4. Ran 2 3/3 5. Will begi Pay Thole a 18. I bereby certify that the SIGNED</pre>	ut out ho: nsity log " 10.5# " injection n injection the follow AUG 5 	true and-correct	1 TD of 2 ck to sur 2833 and h packer -69 3 8 , 39 , 6 9 3 9 , 6 9 3 9 , 6 9 3 9 , 6 9	Petails, and give pertises and measured and performance of the set at 2676' and drives at 2676' and the set at 267	true vertice lled ne 00 sx c 49 sr o 64 6 ECE AUG S. GEOLU ARTESIA	Whole to 28 alss C cemen Si, 52, 55 2468 NED A 1969 A 1969 JGICAL SUNVE DGICAL SUNVE DGICAL SUNVE DGICAL SUNVE	331.
I. Cleaned o 2. Ran GR De 3. Ran 4 1/2 4. Ran 2 3/8 5. Will begi Ref I hole a 18. I bereby certify that f SIGNED	ut out ho: nsity log " 10.5# " injection n injection the follow AUG 5 	true and correct	1 TD of 2 ck to sur 2833 and h packer -69 3 8 , 39 , 6 9 3 9 , 6 9 3 9 , 6 9 3 9 , 6 9	Petails, and give pertises and measured and performance of the set at 2676' and drives at 2676' and the set at 267	true vertice 11ed ne 00 sx c 49 sr o 64 6 ECE AUG S. GEOLU ARTESIA	Whole to 28 alss C cemen Si, 52, 55 2468 NED A 1969 A 1969 JGICAL SUNVE DGICAL SUNVE DGICAL SUNVE DGICAL SUNVE	331.

.

¢