

(SUBMIT IN TRIPLICATE)

Land Office

Santa Fe

Lease No.

N.M. 02427

Unit

OCT 4 1963

RECEIVED

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Leonard Federal July 11, 1961
Well No. 4 is located 1900 ft. from {N} line and 1900 ft. from {E} line of sec. 34
NE 1/4 of SW 1/4 Sec. 34 16-E 30-E N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Square Lake Eddy New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3742 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Subsequent to our verbal conversation of this afternoon, you are advised that we attempted to re-enter the above mentioned well as outlined in our Sundry Notice of June 20, 1961, approved June 26, 1961. However, we were unable to get in the old hole or get clear of junk and never were able to reach a depth to exceed 500'. We then encountered a lost circulation problem up the hole, which we were unable to combat. We then set an umbrella at approximately 175' and filled hole above umbrella with cement and replaced marker, at proper location, according to Gov't. rules and specifications.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company J. Clee Thompson

Address 1203 Kirby Bldg.

Dallas 1, Texas

By Jimmie Thompson
Title Chief Engineer

[illegible]

CONCLUSIONS