

NO. OF COPIES RECEIVED	4
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	2

RECEIVED
NEW MEXICO OIL CONSERVATION COMMISSION
OCT 23 1970

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

D.C.C.
ARTESIA, OFFICE

5a. Indicate Type of Lease State ☒ Fee ☐
5. State Oil & Gas Lease No. E-6484
7. Unit Agreement Name
8. Farm or Lease Name N.E. Square Lake Premier H.
9. Well No. 7
10. Field and Pool, or Wildcat name Square Lake Grayburg SA
12. County Eddy

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER- ☐
2. Name of Operator Mobil Oil Corporation
3. Address of Operator Box 633, Midland, Texas 79201
4. Location of Well UNIT LETTER X 660 FEET FROM THE SOUTH LINE AND 660 FEET FROM THE East LINE, SECTION 3 TOWNSHIP 16-S RANGE 31-E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☒	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Perforate additional pay in same zone AND stimulate as per procedure attached.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J. J. McDaniel TITLE Authorized Agent DATE 10-22-70
APPROVED BY W. A. Gussert TITLE OIL AND GAS INSPECTOR DATE OCT 23 1970
CONDITIONS OF APPROVAL, IF ANY:

MIDLAND E & P DIVISION

WELL WORK RECOMMENDATIONS

Proposals for Well Reconditioning and Subsurface Maintenance
Workovers, Expense DD's, PB's, and Conversions

Lease: N.E. SQUARE LAKE UNIT Well No. 7
Field: N.E. SQUARE LAKE
County: EDDY State: NEW MEX.

RECOMMENDED PROCEDURE:

1. M.I.P.M. Pull ARTIF. LIFT EQUIP.
2. SPOT 1000 gal. 15% FE ACID DOWN HOLE.
3. Pull TRG AND PERFORATE 5 1/2" CSG w/ 1/2" jet
shots (log provided):

3802' - 03'	7 JS
3811' - 17'	7 JS
3823' - 25'	3 JS
3827' - 31'	5 JS
3834' - 42'	9 JS
	31 JS

4. TRAC FORMATION DOWN CSG. w/ 20,000 gal
- Gelled Brine (9#) AND 70,000# 20/40 SAND. ADD
25#/1000 gal ADOMITE AGUA AND 2 gal/1000 gal
SURFACTRON. RECOMMENDED RATE 50 bbl/min.
BLEED IN EVENLY 20 nylon coated ball sealers.

5. SWAB TEST WELL

6. RUN BACK LIFT EQUIPMENT.

WLB K/S 10-6-70

N.E. SQUARE LAKE PREMIER UNIT

WELL # 7

EDDY COUNTY, NEW MEXICO

ELEV 4317'

248'

8 5/8" 36" J55

w/ 150 SX

TOP OF CEMENT 2.242'

3.832'

3.840'

T.D. 3864'

5 1/2" CSG, 14" J55 w/ 280 SX

KS. 10-6-70