

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPI
(Other instructions
reverse side)FE-
re-Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

Federal NM-0162

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

North Square Lake Premier Unit

8. FARM OR LEASE NAME

9. WELL NO.

10

10. FIELD AND ROOM OR WILDCAT
Square Lake Grayburg
San Andres, North11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 5, T16S, R31E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Walsh and Watts, Inc.

3. ADDRESS OF OPERATOR

1111 Seventh Street, Wichita Falls, Texas 76301

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below.)

At surface

1930' FSL and 660' FWL of Section 5, Township 16S,
Range 31E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4026 DF

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☐
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

☐
☐
☒
☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. 10-30-79: Pulled 2100' of 1½" tubing - No recovery on 3462' of 2-7/8" casing or 198' of 7-5/8" casing.
2. 10-31-79: Set a 2-7/8" cement retainer at 2080'.
3. 10-31-79: Plug #1 - 10 sx. 1787' - 2080'.
Plug #2 - Perforated at 1784', set a cement retainer at 1695', cemented with 125 sx.
Plug #3 - Perforated at 697', set a cement retainer at 600', cemented with 100 sx.
Plug #4 - Pumped 45 sx. from 30' to surface.
4. 11-9-79: All pits filled and leveled and location cleared.

18. I hereby certify that the foregoing is true and correct

SIGNED

Alfred B. Guinn

TITLE

Vice-President

DATE

12/4/79

(This space for Federal or State office use)

(Orig. Sgd.) GEORGE H. STEWART

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side