

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRI
(Other instructio
verse side)

Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.
LC-062483

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		7. UNIT AGREEMENT NAME North Square Lake Premier Unit
2. NAME OF OPERATOR Shell Oil Company (Western Division)		8. FARM OR LEASE NAME North Square Lake Premier Unit
3. ADDRESS OF OPERATOR P. O. Box 1509, Midland, Texas 79701		9. WELL NO. 5
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 2970' FSL & 1980' FWL, (Lot 14) Section 5, T-16-S, R-31-E, NMJM Survey, Eddy County, New Mexico.		10. FIELD AND POOL, OR WILDCAT North Square Lake GB/SA
14. PERMIT NO.		11. SEC. T, R, M, OR BLK. AND SURVEY OR AREA Sec. 5, T-16-S, R-31-E NMJM
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4051' DF		12. COUNTY Eddy 13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐
REPAIR WELL ☐	CHANGE PLANS ☐
(Other) Convert to Water Injection ☒	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
(Other) ☐	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Operation: Clean out and convert to water injection.

1. Pull rods, pump and tubing.
2. Clean out to below lowest perforation (3336').
3. Run 2" plastic coated tubing with packer. Circulate casing with fresh water containing 1#/bbl. sodium dichromate. Set packer @ 3300'.
4. Set injection wellhead.

NMCC Order No. R-3016 & R-3017.

RECEIVED

JUL 22 1966

O. C. C.
ARTEZIA, OFFICE

RECEIVED
JUL 22 1966

18. I hereby certify that the foregoing is true and correct

SIGNED N. W. Harrison N. W. Harrison TITLE Senior Exploitation Engineer DATE July 22, 1966

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: _____

APPROVED
JUL 26 1966
H. C. [Signature]
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1963-O-485229

847-831

