

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIE
(Other instruction
verse side)

TE*
re

Form approved
Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO. **NM 1069**
011599 API # 30-015-04810

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON OIL AND GAS Wells. Division

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☐ OIL WELL ☐ GAS WELL ☒ OTHER **Water Injector** **Artesia, NM 88210-2834**

2. NAME OF OPERATOR **Walsh and Watts, Inc.**

3. ADDRESS OF OPERATOR **1111 Seventh Street Wichita Falls, Texas 76301**

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface
Unit Letter "D" or 990' from South line and 330' from East line of Sec. 5, T16S, R31E of NMPM.

7. UNIT AGREEMENT NAME
North Square Lake Premier Unit

8. FARM OR LEASE NAME

9. WELL NO.

19

10. FIELD AND POOL, OR WILDCAT

Square Lake (G/SA) North

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

P - 05 - 16S - 31E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4090.9' G.L.

12. COUNTY OR PARISH

13. STATE

Eddy

New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

XX

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Plug and Abandon injector that is no longer required in waterflood. Procedures should begin July 22, 1999. Well drilled originally by John H. Trigg as the Federal "A" Well No. 8-5.

NOTE: 8-5/8" O.D. set at 859' with 100 sacks (Cement circ.)

4-1/2" O.D. set at 3530' with 100 sacks cement.

- 1.) Set CIBP at 3425' and cap with 35' cement.
- 2.) Circulate hole with mud.
- 3.) Recover 4-1/2" O.D. casing with estimated recovery of 1500'
- 4.) Spot 15 sacks cement 1800' to 1900'
- 5.) Spot 35 sacks cement 1200' to 1300'
- 6.) Spot 35 sacks cement 809' to 909'
- 7.) Spot 104 sacks cement 0' to 290'

**SEE ATTACHED FOR
CONDITIONS OF APPROVAL**

18. I hereby certify that the foregoing is true and correct

SIGNED *Alexis C. Swohoda* TITLE Vice - President

DATE 6/30/99

(This space for Federal or State office use)

APPROVED BY (GRIG. SGD.) ALEXIS C. SWOBODA TITLE PETROLEUM ENGINEER

DATE JUL 19 1999

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side