

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
Revised March 25, 1999

WELL API NO.

30-015-04834

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

NM 026418

7. Lease Name or Unit Agreement Name:

North East Square Lake

8. Well No.

10

9. Pool name or Wildcat

NE Square Lake

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☐ Gas Well ☒ Other

2. Name of Operator

Aghorn Operating Inc.

3. Address of Operator

P O Box 12663

4. Well Location

Unit Letter C : 660 feet from the North line and 1980 feet from the West line

Section 10

Township 16S

Range 31E

NMPM

County Eddy

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

1. 06/12/02 Notified OCD of intent to move in and plug well.

2. 06/13/02 MIRU plugging equipment. RIH w/ 25 jts. 2 3/8 tbg. SDFN.

3. 06/14/02 RIH w/ 115 jts. 2 3/8 tbg. Tag CIBP @ 3600'. Circ. hole w/ 58 bbls. mud laden fluid. Spot 5 sx. class "C" neat cmt on top of CIBP. 3600 - 3528. POH to 2120', pump 25 sx. class "C" neat cmt. WOC 4 hours. Tag cmt. @ 1726'. POOH to 1605'. Pump 50 sx. class "C" neat cmt. POOH, SDFN.

4. 06/17/02 RIH & tag plug @ 908'. POOH w/ tbg. Rig up wireline, perf. 4 1/2 csg. @ 881'. RIH w/ 4 1/2 PKR. set @ 825', pressure up to 1500 psi. Release PKR. POOH. WIH open ended to 893', spot 25 sx. class "C" neat cmt. POOH, SDFN.

5. 06/18/02 RIH & tagged plug @ 587'. POOH, RU wireline, perf. csg. @ 250'. RD wireline, RD BOP & well head, Circ. 85 sx. class "C" neat cmt down 4 1/2 csg. and up 8 5/8 csg to surface. RD, Install Dry Hole Marker, clean loc. Move off.

OCD approval conditional.

Well must meet BLM

Requirements and obtain

Their approval.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Frosty Gilliam TITLE President

DATE 6/20/02

Type or print name Frosty Gilliam

Telephone No. 915-550-0804

(This space for State use)

APPROVED BY [Signature] TITLE Wild Sep ID

DATE JUL 2 2002

Conditions of approval, if any: