

Form 9-331
(May 1963)UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

1E 3527

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR Anadarko Production Company		8. FARM OR LEASE NAME 1E 3527	
3. ADDRESS OF OPERATOR Box 116 Loco Mills, New Mexico 88255		9. WELL NO. 2	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below) At surface 850' TSL - 1668' PWL Sec. 19, T 16 S, R 31 E Sady County, New Mexico		10. FIELD AND POOL, OR WILDCAT Square Lake	
14. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 19 - 16 - 31	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3885 WL		12. COUNTY OR PARISH Sady	
		13. STATE New Mexico	

18. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☒FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Fracture treated well with 15,000 gal. gelled brine and 15,000 sand, 150 scale inhibitor in three equal stages. Treatment was down 2' tubing using straddle packers to treat each zone individually. Treated perfs 3234-41 @ 5000 psi, 5.4 Bpm, ISDP 3400. Treated perfs 3096-3135 @ 5000 psi, 9.4 Bpm, ISDP 2300 psi. Treated perfs 3050-56 5000 psi, 12.3 Bpm, ISDP 2150. Packed tubing and packers washed out well, ran tubing, rods, and pump and returned to production.

RECEIVED

MAY 29 1968

RECEIVED

MAY 28 1968

GEOLOGICAL SURVEY
NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

D. R. Layton

TITLE

District Superintendent

DATE

20 May 1968

(This space for Federal or State office use)

APPROVED

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

APPROVED

MAY 23 1968

R. L. DEANMAN

ACTING DISTRICT SUPERINTENDENT

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.