

UNITED STATES DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

LC-060723

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> WIW - TA		MAR 22 1983	
2. NAME OF OPERATOR NEWMONT OIL COMPANY			
3. ADDRESS OF OPERATOR P. O. BOX 1305 ARTESIA, NEW MEXICO 88210			
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface		660' FSL & 660' FWL of Sec. 29	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3888' GLM	
7. UNIT AGREEMENT NAME SQUARE LAKE FLOOD (East)		8. FARM OR LEASE NAME Texas Trading "A"	
9. WELL NO. 1		10. FIELD AND POOL, OR WILDCAT Square Lake (G.SA)	
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 29-16S-31E		12. COUNTY OR PARISH Eddy	
13. STATE N.M.			

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	<input type="checkbox"/>	PULL OR ALTER CASING	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	MULTIPLE COMPLETE	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	ABANDON*	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
(Other)	<input type="checkbox"/>	(Other)	<input type="checkbox"/>

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

The above well was plugged and abandon as follows....

8/28/82...Set 50 sack plug at 3272'. Loaded hole w/water. SI overnight

8/29/82...Tagged bottom plug at 2709'. Spotted 50 sack plug at 2228'. Squeezed half of it out hole w/800# Pressure..... shut in until Monday.

8/31/82...Tagged plug at 2009'. Pressured up to 800# 15 minutes. Perf. bottom of salt 1470# and squeezed with 50 sacks cement.

9/1/82....Tag plug at base of salt 1327'. Press 1000#. Perf top of salt 685'. Squeezed w/ 120 sacks cement.

9/2/82....Tagged plug at 700'. Set bridge plug at 655'. Perf 620' and squeezed w/100 sacks cement.

9/3/82....Squeezed w/200 sacks cement, WOC 5 hrs. tagged plug at 620' w/wireline, squeezed w/215 sacks, circ. cement to pit, left shut in overnight.

9/4/82....Tag cement at 180' psi to 1000#, Set dry hole marker at surface.

Location ready for inspection

18. I hereby certify that the foregoing is true and correct

SIGNED Emmet J. McLaughlin TITLE Area Manager

(This space for Federal or State use only)

APPROVED BY James A. Gillham TITLE District Supervisor

CONDITIONS OF APPROVAL, IF ANY:

MAR 18 1983

FOR JAMES A. GILLHAM
DISTRICT SUPERVISOR

*See Instructions on Reverse Side

RECEIVED
JAN 17 1983
OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO