

UNITED STATES DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

NM OIL CONS. CO. SECTION  
Artesia, NM 88210

Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-060971

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Square Lake Flood (East)

8. FARM OR LEASE NAME

Fidel

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Square Lake (G. SA)

11. SEC., T., E., M., OR BLK. AND SURVEY OR AREA

Sec. 30-16S-31E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS  
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ WIW -TA

2. NAME OF OPERATOR  
NEWMONT OIL COMPANY

3. ADDRESS OF OPERATOR  
P.O. BOX 1305 ARTESIA, NEW MEXICO 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State regulations. See also space 17 below.)  
At surface

1980' FSL and 660' FEL of Sec. 30

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

XX

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

The above well was plugged and abandon as follows.....

9/11/82....Ran 50 sacks cement plug at 340'.

9/12/82....Tag plug at 2644'. Perf base of salt 1475'. Squeeze w/50 sacks cement @ 200# Pressure.

9/14/82....Plug at base of salt ...did not hold. Squeezed w/100 sacks cement.

9/15/82....Tag plug at base of salt 1190'. PSI to 800#. Perf top of salt at 575'. Squeeze w/150 sacks cement.

9/16/82....PSI on plug at top of salt. 800# Pressure. Tag plug at 390'. Put up dry hole marker.

Location ready for inspection

Posted 12-1-83  
Pda

18. I hereby certify that the foregoing is true and correct

SIGNED

*Lincoln J. McConnel*

TITLE

Area Manager

DATE

1/12/83

(This space for Federal or State Approval)

APPROVED BY *W. CHESTER*  
CONDITIONS OF APPROVAL, IF ANY:

MAR 18 1983

FOR  
JAMES A. GILLHAM  
DISTRICT SUPERVISOR

\*See Instructions on Reverse Side

RECEIVED  
JAN 17 1983

OIL & GAS  
U.S. GEOLOGICAL SURVEY  
ROSWELL, NEW MEXICO