

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN T  
(Other instruct. on re-  
verse side)

Form approved.  
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. NAME OF OPERATOR  
**Newmont Oil Company** ✓
3. ADDRESS OF OPERATOR  
**Room 303, First National Bank Building, Artesia, New Mexico**
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface  
**1980' FSL and 511' FWL of Section 31; T-16-S, R-31-E**

5. LEASE DESIGNATION AND SERIAL NO.  
**NR-0175769**
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME  
**West Square Lake**
8. FARM OR LEASE NAME  
**Grier "A"**
9. WELL NO.  
**1**
10. FIELD AND POOL, OR WILDCAT  
**West Square Lake**
11. SEC., T., S., M., OR B.L. AND SURVEY OR AREA

14. PERMIT NO.
15. ELEVATIONS (Show whether DF, RT, GR, etc.)

**Sec. 31 - 16S - 31E - NPM**

12. COUNTY OR PARISH  
**Eddy**

13. STATE  
**New Mexico**

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

- TEST WATER SHUT-OFF ☐
- PULL OR ALTER CASING ☐
- FRACTURE TREAT ☐
- MULTIPLE COMPLETE ☐
- SHOOT OR ACIDIZE ☐
- ABANDON\* ☐
- REPAIR WELL ☐
- CHANGE PLANS ☐
- (Other) ☐

SUBSEQUENT REPORT OF:

- WATER SHUT-OFF ☐
- REPAIRING WELL ☐
- FRACTURE TREATMENT ☐
- ALTERING CASING ☐
- SHOOTING OR ACIDIZING ☐
- ABANDONMENT\* ☐
- (Other) **Change from TA to Producing**

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

- 7-19-66 Ran # 3/4" bit and rig up reverse unit then cleaned out to 3052'.
- 7-20-66 Clean out to 3060 and pull tubing and bit.
- 7-21-66 Run tubing, pump and rods; waiting on pumping unit.
- 7-22-66 Set pumping unit and put well on production.
- Production first 24 hours 2 BO and 42 BW. Well now making about 2 oil and 10 water.

RECEIVED

JUL 29 1966

D. C. C.  
ARTESIA, OFFICE

RECEIVED  
JUL 29 1966  
U. S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED H. J. LEDBETTER  
(This space for Federal or State office use)

TITLE Division Superintendent

DATE July 29, 1966

APPROVED BY H. L. JENNINGS  
(CONDITIONS OF APPROVAL, IF ANY:)

TITLE

DATE

\*See Instructions on Reverse Side

## Instructions

**General:** This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office. Consult local

**Item 4:** If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

**Item 17:** Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of casing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.