

NO. OF COPIES RECEIVED	2
DISTRIBUTION	
SANTA FE	1
FILE	1 ✓
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED

OCT 18 1973

O. C. C.

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	B-2721

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Kennedy Oil Co., Inc. ✓	8. Farm or Lease Name Doolin
3. Address of Operator Box 151 Artesia, New Mexico 88210	9. Well No. 2
4. Location of Well UNIT LETTER L, 660 FEET FROM THE West LINE AND 1980 FEET FROM THE South 32 TOWNSHIP 16S RANGE 31E N.M.P.M.	10. Field and Pool, or Wildcat Square Lake
15. Elevation (Show whether DF, RT, GR, etc.) 3875 GR	12. County Eddy

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to Plug & Abandon as follows:

3214-20 3258-65
Set bridge plug at 3200' and cap with 5 sx cement plug.
Pull recoverable 5 1/2" casing at freepoint above cement top of 2470'.
Place 100' 35 sx @ 5 1/2" casing stub.
Place 100' 35 sx @ base of salt. 1470-1570
Place 100' 40 sx @ top of salt. 320-420
Place surface plug, regulation marker, and clear up location.

Will advise commission when plugging will commence.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED F. B. Owens TITLE Pres. DATE 10/18/73

APPROVED BY W. A. Gussert TITLE OIL AND GAS INSPECTOR DATE OCT 19 1973

CONDITIONS OF APPROVAL, IF ANY: Intervals between plugs filled w/ mud.