[]			Farm C. 100	
NO. OF COPIES RECEIVED		Form C-103 Supersedes Old		
DISTRIBUTION	NEW MEXICO OIL CONSERVARION CEMINISMON D C-102 and C-103 Effective 1-1-65			
SANTAFE	NEW MEXICO OIL CONS	ENERGY CENTRICATION	Effective 1-1-65	
FILE			5a. Indicate Type of I	Legse
U.S.G.S.	SEP 1 7 1974		State X	Fee
LAND OFFICE		OLI 17 1374	5. State Oil & Gas Le	
OPERATOR 5	PERATOR		B-2721	
		<u> </u>	mmm	mmm.
SUNDRY NOTICES AND REPORTS ON WELLSTESIA, OFFICE (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)				
USE "APPLICATI	ON FOR PERMIT -** (FORM C-101) FOR SUC	H PROPOSALS.)	7. Unit Agreement No	ime
DIL TO GAS	OTHER-			
2. Name of Operator	8. Farm or Lease Name			
Kennedy Oil Co., Inc.			Doolin	
3. Address of Operator	9. Well No.			
Box	1			
4. Location of Well	10. Field and Pool, or Wildcat			
UNIT LETTER N 660 FEET FROM THE South LINE AND 1980 FEET FROM			Square Lake	
THE West LINE, SECTIO	N 32 TOWNSHIP 16S	RANGE JEE NMPN	«/////////////////////////////////////	
mmmmmm	15. Elevation (Show whether	DE RT CR etc.)	12. County	HHHHH
	3889 DF	21, 11, 61, 616,	Eddy	
Čillillillillillillillillillillillillill			<u> </u>	
	Appropriate Box To Indicate N	_		
NOTICE OF IN	TENTION TO:	SUBSEQUEN	IT REPORT OF:	
	ň .	<u></u> -		
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING	CASING
TEMPORARILY ABANDON		COMMENCE DRILLING OPNS.	PLUG AND	ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB		
	r=-1	OTHER		
OTHER				
17. Describe Proposed or Completed Op	erations (Clearly state all pertinent det	ails, and give pertinent dates, includin	g estimated date of star	ting any proposed
work) SEE RULE'1 fos.	orania (orania) araka ara paramana ara		•	-
Danier de alemani	l chanden or Pallarms			
Propose to prug and	l abandon as follows:			
0 4 0 7 1 13 ··· · · 3 ··	0 24000	201		
	ig @ 3100° and cap with	50. cement prug.		
Place heavy mud bet	ween plugs.			
Pull recoverable 52	csg. above cement top	estimated @ 1900'.		
Place 100 cement r	olug @ base of salt 1375	-1475'.	* A.	
Place 100° cement p	olug @ top of salt 4701-	5701. 3400440 1022	7	
Place surface plug, clean, clear and level location and place regulation marker.				
Will advise commission when plugging will commence.				
		of an invested as and ballof	······································	
18. I hereby certify that the information	above is true and complete to the best	of my knowledge and belief.		
\mathcal{O}_{2}			9/1'	7/74
SIGNED 15 Through	4 TITLE	President	DATE	·
110 0	*		ይ ፎቦ -	1 0 1074
APPROVED BY / UCL ATE	CALCA TITLE OIL	AND GAS INSPECTOR	DATE <u>SEP</u>	L Ø 19/4
CONDITIONS OF APPROVAL, IF ANY	·:			
· · · · · · · · · · · · · · · · · · ·				