

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

MAR 20 1975

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

O. C. C.  
ARTESIA, OFFICE

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B-2721
7. Unit Agreement Name
8. Farm or Lease Name State "C"
9. Well No. 2
10. Field and Pool, or Wildcat Square Lake
12. County ddy

SUNDY NOTICES AND REPORTS ON WELLS  
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> <b>Water Injection Well</b>
2. Name of Operator Kennedy Oil Co., Inc. ✓
3. Address of Operator Box 151 Artesia, New Mexico 88210
4. Location of Well UNIT LETTER <b>A</b> <b>660</b> FEET FROM THE <b>North</b> <b>660</b> FEET FROM THE <b>East</b> <b>32</b> LINE, SECTION <b>16S</b> TOWNSHIP <b>31E</b> RANGE <b>31E</b> N.M.P.M.
15. Elevation (Show whether DF, RT, GR, etc.) 3953 DF

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of completion of any proposed work) SEE RULE 1103.

plugged and abandoned as follows:

9/7/74 Set bridge plug @ 3150' and capped with 35' cement plug.  
9/11/74 Cut 5½" casing at 1070' and pulled same.  
Ran tubing and placed heavy mud to 1120'.  
Placed 100' cement plug at 5½" pipe stub 1120'-1020'.  
Placed 100' cement plug @ top of salt 600-700' mud between all plugs.  
Placed surface plug, cleaned, cleared & leveled location.  
Placed regulation marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief

SIGNED [Signature]

TITLE Pres.

3/19/75

APPROVED BY [Signature]

TITLE SUPERVISOR, DISTRICT II

DATE JUL 25 1975

CONDITIONS OF APPROVAL, IF ANY: