

RECEIVED BY
MAR 18 1985
O. C. SUNDY, NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

UNITED STATES DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
NM OIL & GAS DIVISION
Artesia, NM 88210

Form approved.
Budget Bureau No. 42-R1424
5. LEASE DESIGNATION AND SERIAL NO.

LC 060548
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Square Lake Flood (East
8. FARM OR LEASE NAME

Johnson
9. WELL NO.

1
10. FIELD AND POOL, OR WILDCAT

Square Lake (G. SA)
11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

33-16S-31E

12. COUNTY OR PARISH 13. STATE

Eddy N.M.

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ WIW - TA

2. NAME OF OPERATOR

3. ADDRESS OF OPERATOR

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660' FNL & 1980' FWL of Sec. 33 ✓

14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3974' GLM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

The above well was plugged and abandon as follows.....

7/11/82...Set B.P. @ 3310' and capped with 35 sacks cement.

7/13/82....Perf base of salt @ 1710' GLM and squeezed with 50 sacks cement.

7/14/82....Tagged plug at base of salt 1615'. Perf top of salt @ 690'. Squeezed w/110 sacks cement. Circ. to surface.

7/15/82....Tagged top plug at 500'. Set dry hole surface marker...w/15 sacks cmt.

Location ready for inspection

RECEIVED

MAR 23 1983

OIL & GAS
MINERALS INVEST. SERVICE
ROSWELL, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Area Manager

DATE

3/22/83

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

3-15-85

CONDITIONS OF APPROVAL, IF ANY: