

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
NM OIL CONS. COMMISSION
Artesia, NM 88210Form approved.
Budget Bureau No. 42-R1424.

6. LEASE DESIGNATION AND SERIAL NO.

LC-063368

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Square Lake Flood (East)

8. FARM OR LEASE NAME

Texas Trading

9. WELL NO.

6

10. FIELD AND POOL, OR WILDCAT

Square Lake (G.SA)

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 33-16S-31E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL ☐ GAS ☐ OTHER ☐ WIW - TA MAR 22 1983

2. NAME OF OPERATOR
NEWMONT OIL COMPANY O. C. D.

3. ADDRESS OF OPERATOR
P. O. BOX 1305 ARTESIA, NEW MEXICO 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
1980' FSL & 660' FEL of Sec. 33, 16S-31E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

39782 GLM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

The above well was plugged and abandon as follows.....

8/1/82....Spotted 50 sacks cement plug at 3458'. WOC

8/3/82....Tagged bottom plug at 2930'. Had to cut wellhead off and weld collar on 5 1/2" csg.

8/4/82....Leak in csg between 1356' and 1418'. Perf base of salt 1735' and squeezed w/50 sacks cement.

8/5/82....Tag plug. Spotted 50 sacks of cement at 1735' psi to 700#. Perf 725' squeezed w/50 sacks cement at top of salt

8/8/82....Tag cement at 616'. 15x surface plug. Set dry hole marker at surface.

Location ready for inspection.

RECEIVED
JAN 17 1983

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

/Area Manager

DATE 1/12/83

U.S. GEOLOGICAL SURVEY

(This space for Federal or State official use)

APPROVED

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

MAR 18 1983

FOR

JAMES A. GILLHAM
DISTRICT SUPERVISOR

*See Instructions on Reverse Side

POSTED 1/19/83
P. 17