

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPI  
(Other instructions  
verse side)TE\*  
re-Form approved.  
Budget Bureau No. 42-R1424.

Cops to S.F.

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <b>WIW</b>	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR <b>NEWMONT OIL COMPANY</b>	8. FARM OR LEASE NAME <b>Texas Trading</b>
3. ADDRESS OF OPERATOR <b>P. O. BOX 1305, ARTESIA, NEW MEXICO 88210</b>	9. WELL NO. <b>NO. 8</b>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface <b>1270' FNL &amp; 1650' FEL of Sec. 33, T-16S; R-31E</b>	10. FIELD AND POOL, OR WILDCAT <b>SQUARE LAKE</b>
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <b>Sec. 33-16S-31E NMPM</b>
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.)
	12. COUNTY OR PARISH <b>Eddy</b>
	13. STATE <b>New Mexico</b>

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐  
☐  
☐  
☐

PULL OR ALTER CASING

☐  
☐  
☐  
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON\*

REPAIR WELL

CHANGE PLANS

(Other)

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐  
☐  
☐  
☐

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) **Convert to WIW**

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

☐  
☐  
☐  
☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

This well was converted to WIW as follows:

11-15-69 Clean out with sand pump to 3434'.

11-16-69 Ran 6 1/4" bit and clean out to 3645'.

11-17-69 Clean out to 3669'.

11-19-69 Notch well at 3639', 3636', 3633', 3622', 3508', 3504', 3490', 3479', 3473', 3470', 3437', 3428' and then cleaned out to 3661'.

11-20-69 Ran 7" tension packer and set at 2978'.

12-30-69 Rig up and started injection.

Injection first five days averaged 520 bbls at 2550

WFX #302

RECEIVED

MAR 11 1969

O. C. C.  
ARTESIA, OFFICE

RECEIVED

MAR 10 1969  
U. S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

*Charles C. Jay*

TITLE

District Engineer

DATE

3/10/69

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

\*See Instructions on Reverse Side