Form 9-331 (May 1963)

U...TED STATES Drawer Destructions on DEPARTMENT OF THE INTERIOR testa, NM 88210

Form approved, Hudget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

LC 065561 (a)

	GEOL	OGICAL	SURVEY			
SUNDRY	NOTICES	AND	REPORTS	ON	WELLS	

(Do not use this form for proposals to drill or to deepen or plug backer that reservoir.

Use "APPLICATION FOR PERMIT—" for such proposals. 7. UNIT AGREEMENT NAME WE'L WELL WIW - TA MAR 22 1983 Square Lake Flood (East) OTHER 8. FARM OR LEASE NAME 2. NAME OF OPERATOR NEWMONT OIL COMPANY Carper Fed "A" O B Q. C. D. 3. ADDRESS OF OFERATOR 9. WELL NO. P. O. BOX 1305....ARTESIA, N.M. No. 1 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* 10. FIELD AND POOL, OR WILDCAT See also space 17 below.) At surface NO Lake (C.SA) NO BEC. T. R., M., OR BER. AND BURVEY OR AREA 1980' FSL & 660' FEL of Sec. 34 Sec. 34-16S-31E

14. PERMIT NO. :- 15. ELEVATIONS (Show whether DF, RT, GR, etc.)

2. COUNTY OF PARISH 13. STATE
Eddy New Mexico

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:				BUBSEQUENT REPORT OF:			
TEST WATER SHUT-OFF		PULL OR ALTER CASING		WATER SHUT-OFF REPAIRING WELL			
FRACTURE TREAT		MULTIPLE COMPLETE		FRACTURE TREATMENT ALTERING CASING			
BHOOT OR ACIDIZE		ABANDON*	<u> </u>	SHOOTING OR ACIDIZING ABANDONMENT*			
REPAIR WELL		CHANGE PLANS		(Other)			
(Other)				(Norr: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)			
and also posterior of court with approximate All contractions details and also posting a later including actimated data of starting							

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

The above well was plugged and abandon as follows.....


10/2/82....Spotted 50 sack plug at 3436'.

10/5/82....Pressure tested casing, held. Tagged plug at 3008'. Shot bottom of salt @ 1870'.

10/6/82....Tagged plug at 1590'. Shot top of salt 4 shots at 875'. Squeezed 200 sacks cmt

10/7/82.....Tagged plug 335'. Pressured plug to 800 psi. Held. Set dry hole surface marker.

Location ready for inspection



JAN 26 1983

OIL & CAS
MINERALS MONT, SERVICE
ROSWELL NEW MEXICO

		DSWELL, NEW MEXICO
SIGNED AND AND TITLE	Area Manager	DATE 1/25/83
APPROVED BY (SEE) PETER W. CHESTER TITLE CONDITIONS OF APPROVAL, WANTER 1980 FOR JAMES A. GILLHAM DISTRICT SUPERVISOREE Instruc	tions on Reverse Side	DATE OF THE POST