

(May 1963)

UNITED STATES DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Project Number No. 42-11424  
D. LEASE TERMINATION AND SERIAL NO.  
LC 065561 (a) 451  
C. D. INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ WIL - TA  
2. NAME OF OPERATOR Newmont Oil Company  
3. ADDRESS OF OPERATOR P. O. Box 1305 - Artesia, N.M. 88210  
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface  
1980' FNL & 660' FWL of Sec. 34  
14. PERMIT NO.  
15. ELEVATIONS (Show whether DF, RT, GR, etc.)  
4002' GLM

RECEIVED

MAR 28 1983

O. C. D.

ARTESIA OFFICE

7. UNIT AGREEMENT NAME  
Square Lake Flood (East)  
8. FARM OR LEASE NAME  
Carper Federal  
9. WELL NO.  
3  
10. FIELD AND POOL, OR WILDCAT  
Square Lake (G. SA)  
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
Sec. 34-16S-31E  
12. COUNTY OR PARISH  
Eddy  
13. STATE

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

The above well was plugged and abandon as follows.....

10/14/82...Spotted 50 sacks cement at 3469'.

10/15/82...Tagged plug at 3224'. Perf base of salt at 1770'. Squeezed w/50 sacks cement

10/16/82...Tagged plug at 1566'. Perf top of salt @ 760'. Squeezed 200 sacks cement.

10/17/82...Tagged plug at 175'. Set 15 sacks plug and dry hole marker.

Location ready for inspection

RECEIVED

MAR 23 1983

OIL & GAS  
MINERALS MONIT. SERVICE  
ROSWELL, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Area Manager

DATE

3/22/83

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side

Post ID-2  
4-1-83  
P-14