

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT TO COMMISSION  
(OTHER INSTRUCTIONS ON REVERSE)  
Form approved.  
Budget Bureau No. 42-R1424.  
5. LEASE DESIGNATION AND SERIAL NO.  
Artesia, NM 88210 LC-029438 (B)

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

|   |  |   |  |
|---|--|---|--|
| 1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> WTW-JA   |  | 7. UNIT AGREEMENT NAME<br>Square Lake Flood                         |  |
| 2. NAME OF OPERATOR<br>Newmont Oil Company  |  | 8. FARM OR LEASE NAME (East)<br>Garner Fed                          |  |
| 3. ADDRESS OF OPERATOR<br>P. O. Box 1305, Artesia, New Mexico 88210   |  | 9. WELL NO.<br>5  |  |
| 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)<br>At surface<br>1980' FSL AND 1980' FWL of Sec. 34 |  | 10. FIELD AND POOL, OR WILDCAT<br>Square Lake (G. SA)               |  |
| 14. PERMIT NO.  |  | 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA<br>Sec. 34-16S-31E |  |
| 15. ELEVATIONS (Show whether DF, RT, GR, etc.)<br>4009' GLM ARTESIA, OFFICE   |  | 12. COUNTY OR PARISH<br>Eddy  |  |
|   |  | 13. STATE<br>New Mexico   |  |

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON\* ☒CHANGE PLANS ☐

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT\* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

We propose to plug and abandon the above well as follows:

1. Pull tubing and packer.
2. Spot 50 sack cement plug across producing interval in cased hole.
3. Perforate at base of salt 1795', squeeze with 50 sacks cement leaving 100' plug in casing.
4. Perforate at top of salt 803', and squeeze with 50 sacks cement leaving 100' plug in casing.
5. Set 15 sack cement plug at surface down surface and production casing.
6. Erect permanent well marker

Note:

- (a.) Your office will be notified 24 hrs. prior to operations
- (b.) All plugs will be verified
- (c.) Hole will be loaded between all plugs with 10# mud
- (d.) We do not plan to pull any casing

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Area Manager

DATE 9/2/82

(This space for Federal or State office use)

APPROVED BY (P. S. S.) PETER W. CHESTER  
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

FOR

JAMES A. GILLHAM \*See Instructions on Reverse Side  
DISTRICT SUPERVISOR