

UNITED STATES DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

NM OIL & GAS COMMISSION
Artesia, NM 88210

Form approved.
Budget Bureau No. 42-R1424.

6. LEASE DESIGNATION AND SERIAL NO.

LC-065561

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

SQUARE LAKE FLOOD (EAST)

8. FARM OR LEASE NAME

JOHNSON

9. WELL NO.

17

10. FIELD AND POOL, OR WILDCAT

Square Lake (G. SA)

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 34-16S-31E

12. COUNTY OR PARISH 13. STATE

Eddy New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

1. OIL WELL ☐ GAS WELL ☐ OTHER ☐

WIW - TA

MAR 22 1983

2. NAME OF OPERATOR

NEWMONT OIL COMPANY

3. ADDRESS OF OPERATOR

P. O. BOX 1305 ARTESIA, NEW MEXICO ARTESIA, OFFICE

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

2310' FNL 1980' FEL of Sec. 34

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4027' GLM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

The above well was plugged and abandon as follows.....

7/21/82....Set plug at 3700'. Tagged plug at 3454'. Ran 2nd plug of 60 sxs cmt.

7/22/82....Tag bottom plug at 1900 ft. Perf base of salt at 1800' and squeezed w/50 sacks cement @ 600 psi.

7/23/82....Tag plug at base of salt....1715'. Pressured up to 600#. Perf top of salt at 830' and squeezed with 50 sacks cement @ 400#.

7/24/82....Tag plug at top of salt 695'. Spot 50 sacks cement at 695'. Squeezed casing leak between 260' and 414' psi 600#. Perf base of surface csg 95'. Circ. with 65 sacks cement. Put up dry hole marker

Location ready for inspection

RECEIVED
JAN 17 1983

18. I hereby certify that the foregoing is true and correct

SIGNED

James A. Gillham

TITLE

Area Manager

OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSW/DATE 1/12/83

(This space for Federal or State Use)
(Orig. S...) PETER W. CHESTER

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

MAR 18 1983

FOR

JAMES A. GILLHAM
DISTRICT SUPERVISOR

TITLE

DATE

*See Instructions on Reverse Side