

RECEIVED BY

AUG 14 1985

O.C.D.

ARTESIA OFFICE

DEPARTMENT OF THE INTERIOR

GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

WELL ☐ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

NEWMONT OIL COMPANY Yates Pet. Co.

3. ADDRESS OF OPERATOR

P.O. BOX 1305 ARTESIA, NEW MEXICO 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface

2310' FNL 1980' FEL of Sec. 34

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4027' GLH

6. LEASE DESIGNATION AND SERIAL NO.

LC-065561

8. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

SQUARE LAKE FLOOD (EAST)

8. FARM OR LEASE NAME

JOHNSON

9. WELL NO.

17

10. FIELD AND POOL, OR WILDCAT

Square Lake (G. SA)

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 34-16S-31E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

13. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☐
☐
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐
☐
☐

REPAIRING WELL

☐
☐
☐
☐
☒

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

The above well was plugged and abandon as follows.....

7/21/82....Set plug at 3700'. Tagged plug at 3454'. Ran 2nd plug of 60 sxs cmt.

7/22/82....Tag bottom plug at 1900 ft. Perf base of salt at 1800' and squeezed w/50 sacks cement @ 600 psi.

7/23/82....Tag plug at base of salt....1715'. Pressured up to 600#. Perf top of salt at 830' and squeezed with 50 sacks cement @ 400#.

7/24/82....Tag plug at top of salt 695'. Spot 50 sacks cement at 695'. Squeezed casing leak between 260' and 414' psi 600#. Perf base of surface csg 95'. Circ. with 65 sacks cement. Put up dry hole marker

Location ready for inspection

18. I hereby certify that the foregoing is true and correct

SIGNED

Robert J. McGonigill

TITLE

Area Manager

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

RECEIVED
JAN 17 1983

OIL DATE

1/12/83

GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

8-12-85