

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

NM OIL CONS. COMMISSION
Drawn DD IN DUPLICATE
Altesia, NM 88210

Form approved.
Budget Bureau No. 42-10342-

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or plug back to a well.
Use "APPLICATION FOR PERMIT" for such proposals.

1. TYPE OF WELL
☐ GAS WELL ☐ WATER WELL ☐ OTHER

Water Injection Well

MAR 21 '88

2. NAME OF OPERATOR

Boyd Operating Company

3. ADDRESS OF OPERATOR

P. O. Box 1756, Roswell, New Mexico 88203

O. C. D.
ARTESIA, OFFICE

4. LOCATION OF WELL (Report location clearly and in accordance with any State law or rule.
See also space 17 below.)
At surface

2002 FNL, 1980 FEL, Section 35

11. TRIBUT NO

12. ELEVATIONS (Show whether DE, FL, GR, etc.)

4082'

5. LEASE DESIGNATION AND SERIAL NO.

LC 029438A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Carper Johnson 'A'

9. WELL NO.

1-Y

10. FIELD AND POOL OR WILDCAT

Gbg Jackson Queen G-FF

11. SEC. T., R., M., OR BLE, AND
SURVEY OR AREA

Sec. 35 T16S, R-31E

12. COUNTY OR PARISH 13. STATE

Eddy

N Mex

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WELL SHUT-OFF

REPAIRING WELL

FRAC TREAT

MULTIPLE COMPLETION

FRAC RE TREATMENT

ALTERING CASING

STIMULANT ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

(Other)

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. EXPLANATION OF WORK (If applicable, state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is being shut in, give subsurface locations and numbered and true vertical depths for all markers and zones perti-
nent to this work.)

Had bit stuck at 3020'. Unable to recover push down hole.

- 1) Mixed 25 sx plug and spotted from 2865' to 3013'.
- 2) Mixed heavy gelled mud from 2856' to 3030'.
- 3) Spotted 25 sx plug from 1942' to 1790' - base of salt.
- 4) Mixed and spotted gel from 1758-975'.
- 5) Perforated @ 975'. Mixed 50 sx cement plug.
- 6) Displaced plug with heavy gel. Pumped 3 1/2 bbl. cement out perforations, 7 bbl. in 7" csg.
- 7) Pumped 10 sx. plug at surface.
- 8) PAA Set well marker.

Ran cement bond log, PAA as per Mondo Lopez & John Wade.

SJS

I hereby certify that the foregoing is true and correct.

SIGNED

TITLE

Operator

DATE

9/24/82

This space for Federal or State use only

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL IF ANY:

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*

Form approved
Budget Bureau No. 42-R1424

MINERAL OIL CONS. COMMISSION

CASE DESIGNATION AND SERIAL NO.

Drawer DD

LC 029438A

SUNDRY NOTICES AND REPORTS ON WELLS

Artesia, NM 88210

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.

1. WELL TYPE: ☐ OIL WELL ☐ GAS WELL ☐ OTHER ☒ Water Injection Well

MAR 21 '88

7. UNIT AGREEMENT NAME

2. NAME OF OPERATOR

Boyd Operating Company

8. FARM OR LEASE NAME

Carper Johnson "A"

3. ADDRESS OF OPERATOR

ARTESIA, OFFICE

9. WELL NO.

1-Y

P. O. Box 1756, Roswell, New Mexico 88201

4. LOCATION OF WELL (Report location clearly and in accordance with any State regulations.
Specify space if below surface)

10. FIELD AND POOL, OR WELDCAT

Gbg Jackson Queen-2-A

11. SEC. T., R., M., OR BLM. AND
SURVEY OR AREA

Sec. 35 T16S, R-31E

12. PERMIT NO.

13. ELEVATIONS (Show whether DE, RT, CR, etc.)

4082'

12. COUNTY OR PARISH

Eddy

13. STATE

N Mex

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

PULL OR ALTER CASING ☐

FRACURE TREAT ☐

MULTIPLE COMPLETION ☐

SHOOT OR ACIDIZE ☐

ABANDON* ☐

REPAIR WELL ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

REPAIRING WELL ☐

FRACURE TREATMENT ☐

ALTERING CASING ☐

SHOOTING OR ACIDIZING ☐

ABANDONMENT* ☒

Other: ☐

Name. Report results of multiple completion on Well
(Completion or Re-completion Report and Log form.)

14. IS WELL PROPOSED OR COMPLETED OPERATIONS (Check appropriate box and also completion dates including estimated date of starting any proposed work. If well is down only drilled, show subsurface location of casing and true vertical depth for all intervals and zones pertinent to this work.) *

Had bit stuck at 3020'. Unable to recover push down hole.

- 1) Mixed 25 sx plug and spotted from 2865' to 3013'.
- 2) Mixed heavy gelled mud from 2856' to 1930'.
- 3) Spotted 25 sx plug from 1942' to 1796' - Base of salt.
- 4) Mixed and spotted gel from 1758-975'.
- 5) Perforated @ 975'. Mixed 50 sx cement plug.
- 6) Displaced plug with heavy gel. Pumped 3 1/2 bbl. cement out perforations, 7 bbl. in 7" csg.
- 7) Pumped 10 sx. plug at surface.
- 8) P&A Set well marker.

Ran cement bond log, P&A as per Mondo Lopez & John Wade.

I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Operator

DATE

9/24/82

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF ADEQUACY IF ANY: