FRACTURE TREAT

REPAIR WELL

SHOOT OR ACIDIZE

Form approved

Form 9-331		NITED STATES	SUBMIT IN PLICAL Other instrums on		No. 42-R1424.	
(May 1963)	DEPAR'I MENT OF THE INTERIOR (Other instr. us of re-			5. LEASE DESIGNATION	5. LEASE DESIGNATION AND SERIAL NO.	
		GEOLOGICAL SURVEY			6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
		6. IF INDIAN, ALLOTTEE				
Sl (Do not use t	INDRY NOT	ICES AND REPORTS tals to drill or to deepen or plu ATION FOR PERMIT—" for such	g back to a different reservoir.			
	OBE ATTESO	7. UNIT AGREEMENT NA	7. UNIT AGREEMENT NAME			
OIL GAS WELL WEI	L OTHER	Re-Entry			D	
2. NAME OF OPERATO	R		8. FARM OR LEASE NAME			
Yates Petr	oleum Corp	Simpson "A	Simpson "AQ"			
3. ADDRESS OF OPER.	TOB	9. WELL NO.	9. WELL NO.			
309 Carper		1	1			
4. LOCATION OF WELL	Bulluling (Banant legation of	10. FIELD AND POOL, OF	10. FIELD AND POOL, OR WILDCAT			
See also space 17	below.)	Wildcat	Wildcat 11. SEC., T., B., M., OR BLK. AND SUBVEY OR AREA			
At surface		11. SEC., T., B., M., OR B SURVEY OR AREA				
6601	FNL and 1	Sec. 30-16S	Sec. 30-16S-29E .			
14 PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)			12. COUNTY OR PARISH 13. STATE			
14. PERMIT NO.		3670		Eddy	N.Mex	
16.	Chack A	propriete Box To Indicate	Nature of Notice, Report,	or Other Data		
				BSEQUENT REPORT OF:		
	NOTICE OF INTER	ITION TO:				
TEST WATER SH	CT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING V	VELL	
IEGI WALDE DII	i -	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING C.	ASING	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) * (Other)

We plan to Plug and Abandon this well as follows:

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

Set 100' plugs from 2930-2830'; 1930-1830'; 1500-1400'; 375-275' and a 20' plug to surface with Regulation dry hole marker. Heavy mud will be used between the plugs.

SHOOTING OR ACIDIZING

RECEIVED

JUN-81967

JUN-81967

U. S. GEOLOGICAL SURVE

NEW MEXICO

ABANDONMENT*

18. I hereby certify that the foregoing is true and correct			6 6 67
18. I hereby certify that the foregoing is true and correct SIGNED /// () () () () () () () () ()	TITLE	Agent	6-8-67
(This space for Federal or State office use		, "u !	DATE JUN 9 1967
APPROVED BY PROVAL IF ANY:	TITLE		