

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLY
(Other instructions
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

01171-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

West Henshaw Unit Tract 7-3

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Henshaw Grayburg West

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 3, T-16-S, R-30-E

12. COUNTY OR PARISH

Eddy

13. STATE
New MexicoSUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ WIN

2. NAME OF OPERATOR

Mobil Oil Corporation

3. ADDRESS OF OPERATOR

P. O. Box 633, Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

Unit E, 2310' FNL & 660' FML, Sec. 3, T-16-S, R-30-E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) * **RECOMMENDED PROCEDURE:**

- 1) Pull injection equipment.
- 2) Set a CIBP @ 2730' + and cap w/35' of Neat cement (6sx)
- 3) Load the hole w/mud laden fluid using 25sx of gel/100 bbls. water (9.5# Brine-minimum weight)
- 4) Determine the free point, cut, and pull the 5 1/2"-14#/ft. csg
- 5a) If the free point and cut-off is below 1650', set 100' cmt plug in the 5 1/2" csg w/50' below and 50' above the cut-off point, (25sx min); and set 100' cmt from 1100'-1200' across bottom of salt, (35sx)
- 5b) If the cut-off is at or above 1650', set a 100' cmt plug in the the 5-1/2" csg stub w/50' below and 50' above the cut-off point (25sx min)
- 6) Set a 122' cmt plug across the 8-5/8" csg seat from 320'-442' (40sx). This plug also covers the salt top @ 370'
- 7) Set a 10' plug @ Surface (10sx min)
- 8) Erect Monument.

RECEIVED

AUG 9 1976

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Authorized Agent

DATE 8-5-76

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

APR - 2 1976

ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

RECEIVED

1967

U.S. GOVERNMENT PRINTING OFFICE