

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

MAY 09 1994

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-015-10205
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. LG#6339
7. Lease Name or Unit Agreement Name Humble State "23"
8. Well No. 1
9. Pool name or Wildcat Undesignated Premien
10. Elevation (Show whether DF, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator MARBOB ENERGY CORPORATION	3. Address of Operator P.O. Drawer 217, Artesia, N.M. 88210	4. Well Location Unit Letter <u>I</u> : <u>972</u> Feet From The <u>East</u> Line and <u>1989</u> Feet From The <u>South</u> Line Section <u>23</u> Township <u>17S</u> Range <u>28E</u> NMPM Eddy County
---	--	--	---

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

(1) Set 5½ CIBP @2100', spot 25 sks cement on top of CIBP
(2) Load hole w/mud
(3) Cut and pull 5½ casing @1030
(4) Spot 25 sks cement plug @ 1470'
(5) Spot 25 sks cement plug @5½ stub, 1080', W.O.C. Tag cement top @982'
(6) Spot 35 sks cement plug @8 5/8 shoe, 558', W.O.C., did not tag cement plug
Respot 40 sks cement plug @558', W.O.C., Tag cement plug top @ 433'
(7) Spot 10 sks cement plug @ surface, set P&A marker

Post ID-2
6-3-94
PFA

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE District Secretary DATE 5-3-94

TYPE OR PRINT NAME _____ TELEPHONE NO. _____

(This space for State Use)

APPROVED BY [Signature] TITLE AND GAS INSPECTOR DATE 4-6-95

CONDITIONS OF APPROVAL, IF ANY: _____