

Submit 3 Copies To Appropriate District

Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM

87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103

Revised March 25, 1999

WELL API NO.

30-015-~~02130~~ 10313

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name:

Empire Abo Unit

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other SWD

2. Name of Operator

B-P America Production Co.

3. Address of Operator

P.O. Box 1089, Eunice, New Mexico 88231

4. Well Location

Unit Letter B : 990 feet from the North line and 900 feet from the East line

Section 32 Township 17S Range 28E NMPM Eddy County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

KB= 10' above GL

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

PROCEDURE TO P&A. No uphole potential. T.D. 6148'. PBTD 6114'. CIBP @ 5879'.

(1) MIRU pulling unit. ND well head. NU BOP & Enviro-vat.

(2) TIH & tag CIBP @ 5870'.

(3) Circulate hole w/9.5# salt gel mud.

(4) Cap CIBP @ 5870' w/25sxs. cmt.

(5) RIH w/wireline & perf 4 1/2 csg. @ 3360' POH w/WL.

(6) RIH w/4 1/2 AD-1 pkr. & tbgr. Squeeze 35 sxs. cmt. from 3360' to 3260'. Glorieta.

(7) POH w/tbgr. & pkr.

(8) RIH w/wireline & perf csg. @ 1054'. POH w/WL.

(9) RIH W/4 1/2 AD-1 pkr. & tbgr. Squeeze 4 1/2 & 8 5/8 csg. w 50 sxs, cmt. from 1054' to 954'. WOC & tag shoe plug.

(10) POH w/tbgr. & pkr.

(11) RIH w/wireline & perf 4 1/2 csg. @ 600'. POH w/WL.

(12) RIH w/AD-1 pkr. & tbgr. Squeeze 4 1/2 & 8 5/8 csg. w/35 sxs. cmt. from 600' to 500'. Yates plug.

(13) POH w/ tbgr. & pkr.

(14) RIH w/wireline & perf csg. @ 60'.

(15) Squeeze 10 sxs. cmt. around 4 1/2 & 8 5/8 csg. to surface.

(16) Cut off well head & anchors 3' BGL. Set dry hole marker. Clean up location.

325 - 425

Notify OCD 24 hrs. prior to any work done.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kellie D. Murrish TITLE SR. Admin. Asst. DATE 12.11.02

Type or print name Kellie D. Murrish Telephone No. 505.394.1600

APPROVED [Signature] TITLE Field Rep ID DATE DEC 31 2002

Conditions of approval, if any.