

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

CISK

Form C-103
Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-015-10360
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other <input checked="" type="checkbox"/> Injection		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator Read & Stevens, Inc.		6. State Oil & Gas Lease No. E-8560
3. Address of Operator P. O. Box 1518 Roswell, New Mexico 88202		7. Lease Name or Unit Agreement Name: BHWFU (Formerly Bogle Farms #1)
4. Well Location Unit Letter L : 1980 feet from the South line and 660 feet from the West line Section 13 Township 16S Range 31E NMPM County Eddy		8. Well No. 9
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 4,396' GR		9. Pool name or Wildcat Bunker Hill Penrose

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

11/02/02 Set CIBP @ 3,300', spot 20 sx on top 3,150'.
11/05/02 Spot 50 sx @ 2,400'-2,239' & tag.
11/05/02 Spot 50 sx @ 1,342'-1,217' & tag.
11/06/02 Pulled 418' of 4 1/2" casing.
11/06/02 Spot 75 sx @ 469'-344' & tag.
11/06/02 Spot 50 sx @ 344'-295' & tag.
11/07/02 Spot 40 sx @ 295'-232'.
11/07/02 Spot 40 sx @ 60' to surface.

Install dry hole marker.
Circulate 10# mud.
Move in & rip location. Reseed with native grasses.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE John C. Maxey, Jr. TITLE Operations Manager DATE 1-8-03
Type or print name John C. Maxey, Jr. Telephone No. 505/622-3770

(This space for State use)
APPROVED BY [Signature] TITLE Field Rep ID DATE JAN 13 2003
Conditions of approval, if any