

December 5, 1966

G. Kelly Stout  
Drawer AA  
Artesia, New Mexico

Re: Superior Stout No. 2 P  
12-17-28

Dear Mr. Stout:

A recent field inspection of the subject well site reveals the following: There is junk on the location and the pits have not been filled. Further, the hole is collapsing under the surface marker pad. Therefore, the marker must be removed and the hole properly plugged to prevent further collapse. Please proceed with all required work at your earliest convenience. This office must be contacted prior to the plugging operation as we may wish to have a representative there at that time.

Very truly yours,

OIL CONSERVATION COMMISSION

R. L. Stamets  
Geologist

RLS/bh