(SUBMIT IN TRIPLICATE) UNITED STATES DEPARTMENT OF THE INTERIOR RECEIVED RICT ENGINEER JUN _ 5 1964 ices and repo O. C. C. ARTESIA, OFFICE SUBSEQUENT REPORT OF WATER SHUT-OFF..... NOTICE OF INTENTION TO DRILL NOTICE OF INTENTION TO CHANGE PLANS SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING..... NOTICE OF INTENTION TO TEST WATER SHUT-OFF..... SUBSEQUENT REPORT OF ALTERING CASING..... SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR. NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.... SUBSEQUENT REPORT OF ABANDONMENT..... NOTICE OF INTENTION TO SHOOT OR ACIDIZE..... SUPPLEMENTARY WELL HISTORY NOTICE OF INTENTION TO PULL OR ALI'ER CASING. NOTICE OF INTENTION TO ABANDON WELL (INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA) JUNE 19, Well No. FEDERAL is located 1650 ft. from: $\{S\}$ line and 1346 ft. from $\{W\}$ line of sec. 30. SQUARE LAKE The elevation of the derrick floor above sea level is _____ft. DETAILS OF WORK (State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cement-ing points, and all other important proposed work) ON JUNE 10, 1964, TUBING AND RODS WERE PULLED FROM THIS WELL, AND A RETREIVABLE BRIDGE PLUG WAS SET AT 3107' BETWEEN THE TWO SETS OF PERFORATIONS AT 3087'-89' AND 3135'-46.5'. THE UPPER PERFORATIONS FROM 3087'-89' WERE PRESSURE TESTED AND FOUND NOT TO BE OPEN. APPARENTLY ALL OF FIRST FRAC JOB WENT OUT LOWER SET OF PERFORATIONS FROM 3135'-46.5'. THE UPPER PERFORATIONS WERE BROKEN DOWN AND TREATED W/ SLICK WATER AND 7300# Before fracturing upper zone, well was producing 5 BOPD. Well is now producing 26 BOPD.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.	
Company WATER-FLOOD ASSOCIATES, INC.	
Address 2211 CONTINENTAL NAT'L BANK BLDG.	
Fort Worth, Texas 76102	By Cas. Standalls
	Title Co-ordinator waterflood operations