

UNITED STATES DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

TE
re

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐ *Injection well*

2. NAME OF OPERATOR *ARWOOD, LTD.*

3. ADDRESS OF OPERATOR *P. O. Box 64548, Dallas, Texas 75206*

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
330 FNL 1995 FWL

5. LEASE DESIGNATION AND SERIAL NO.
NM 07781

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
LOE FEDERAL

9. WELL NO.
3

10. FIELD AND POOL, OR WILDCAT
Sq Lake Gbg SA

11. SEC., T., E., M., OR BLK. AND SURVEY OR AREA
30-16S-31E

12. COUNTY OR PARISH
Eddy

13. STATE
NM

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3828

RECEIVED

AUG 5 1977

D. C. C.
ARTESIA, OFFICE

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	<input type="checkbox"/>	PULL OR ALTER CASING	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	MULTIPLE COMPLETE	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	ABANDON*	<input checked="" type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
(Other)	<input type="checkbox"/>	(Other)	<input type="checkbox"/>

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

13" @ 30' w/20 sacks reg.
11" hole to 420', 7 7/8" hole to 3275'.
5 1/2", 15# 0-536' & 3242' to 3274'
5 1/2", 14.4# 536' to 3242', cemented with 150 sx w/4% gel followed by
150 sx. regular. 50 sx. neat @ 400' with 1" tubing.

PLUG AND ABANDON

1. Spot a cement plug across perforations 3218-30' (min. of 100')
2. Spot a cement plug across perforations 3037-85' (min. of 100')
3. Spot 100' cement across top of salt at 400'.
4. Spot 25' plug at surface, install marker and cleanup location.

Gelled mud (25 sacks/100 bbls. water) between each cement plug.

RECEIVED

JUN 29 1977

U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED *T. M. Boyd* TITLE *Agent*

DATE *6/28/77*

(This space for Federal or State office use)

APPROVED BY *Joe J. Lara*
CONDITIONS OF APPROVAL, IF ANY:

TITLE *ACTING DISTRICT ENGINEER*

DATE *AUG 4 - 1977*