Submit 3 Copies to Appropriate District Office

DISTRICT I

DISTRICT II

P.O. Box 1980, Hobbs, NM 88240

P.O. Drawer DD, Artesia, NM 88210

APPROVED BY The CONDITIONS OF APPROVAL, IF ANY:

State of New Mexico merals and Natural Resources Department Energy.

ION

C-103 sed 1-1-8

C

WELL API NO.

TITLE Field Rop. II DATE 1/12/2001

Energy,merais and material resources Dep
OIL CONSERVATION DIVIS
2040 Pacheco St.

Santa Fe, NM 87505

30-015-10480		
ndicate Type of Lease		
	STATE	FEE

							STATE	FEE			
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410							∘State Oil & Gas Leas	se No.			
SUNDRY NOTICES AND REPORTS ON WELLS									en jetr		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)								7Lease Name or Unit Agreement Name			
								Five J			
οĩ	/pe of Well: L ELL	GAS WELL	/		OTHER						
	ame of Operat ck Energy (or Corporation						₃Well No. 1			
3A(dress of Ope	ator						∘Pool name or Wildca	at	• • • •	
P.O. Box 960, Artesia, NM 88211-0960							Artesia Queen (Grayburg SA			
٠W	ell Location				_						
	Unit Letter	<u> </u>	_ Feet From	The	South	Line and _	330	Feet From The	East	Line	
25	Section	178	Town	ship	28E	Range		NMPM	Eddy	County	
				₁₀Elevat	on (<i>Show whether</i> i	DF, RKB, RT, GR, €	etc.)				
•										· ·	

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PLUG AND ABANDON REMEDIAL WORK ALTERING CASING PERFORM REMEDIAL WORK **TEMPORARILY ABANDON CHANGE PLANS** COMMENCE DRILLING OPNS. PLUG AND ANBANDONMENT **PULL OR ALTER CASING** CASING TEST AND CEMENT JOB OTHER: OTHER: 12Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Notify 24Hrs. Before starting 1. MIRU POH W/ tubing & pkr (loc set & tandem pkr) 2.RIH spot 100' @ 2100 (perf. 2237 to 2343). 3. Perf. @ 700 sqz. 100' plug (salt 602) Perf. 800. 3. Pert. @ 700 sqz. 100' plug (sair ouz) 7717. 0000
4 Pert @ 450' sqz. 100' plug (8 5/8 shoe @ 400') Pert 457'. Sq.z. 100' cmt. Insider
5. Spot 60' plug @ surface
407' outsid (5'/2' cri. IDL 6. cut off well head install dry hole marker 5. Perforate 5th" cs > 50'. Circulate cement to surface. Inside + Outside 51/2" casing. * Brine gel between All coment Plug Net If it N. M. C. (D. To witness Plussing Operations.

Thereby certify that the information above is true and complete to the best of my knowledge and delief. DATE 01-09-01 TELEPHONE NO. 915 5807161 TYPE OR PRINT NAME Wayne Brooks (This space for State Use)