

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	
LAND OFFICE	<input checked="" type="checkbox"/>
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION  
RECEIVED

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

AUG - 3 '90

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-9220
7. Unit Agreement Name
8. Farm or Lease Name Pan American 13 State
9. Well No. 1
10. Field and Pool, or Wildcat
12. County Eddy

SUNDY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- ARTESIA, OFFICE
2. Name of Operator Remuda Operating Company
3. Address of Operator 301 N. Colorado, Ste. 150, Midland, Tx. 79701
4. Location of Well UNIT LETTER <u>A</u> <u>660</u> FEET FROM THE <u>East</u> LINE AND <u>660</u> FEET FROM THE <u>North</u> LINE, SECTION <u>13</u> TOWNSHIP <u>16S</u> RANGE <u>31E</u> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 4382 GR

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8 5/8 set @ 417' cemented with 225 sx. 2 7/8 tubing set @ 3398' as production string cemented with 80 sx. Perfs 3356-58 & 3362-70.

Spot 10 sx plug @ 3356', pull 2 7/8 and spot 25 sx @ cutoff & tag. Spot 100' plug @ ~~2150-2250~~, 100' plug @ ~~1200-1300~~, 50 sx plug @ 8 5/8, 10 sx plug @ top.

~~2200-2300~~ TAG ~~1300-1400~~ TAG ~~467-362~~ TAG - n.s.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Nert Fisher TITLE Agent DATE 8/1/90  
APPROVED BY Daniel Moore TITLE Geologist DATE 8/21/90  
CONDITIONS OF APPROVAL, IF ANY: