

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P.O. Box 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S	
LAND OFFICE	
OPERATOR	

JUL 29 1983

O. C. D.
ARTESIA, OFFICE

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>	
5. State Oil & Gas Lease No. E-8560	
7. Unit Agreement Name -	
8. Farm or Lease Name Bogle Farms Com.	
9. Well No. 2	
10. Field and Pool, or Wildcat Mesa Queen	
12. County Eddy	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT-" (FORM C-1011 FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/>	GAS WELL <input checked="" type="checkbox"/>	OTHER
2. Name of Operator Read & Stevens, Inc.		
3. Address of Operator P.O. Box 1518, Roswell, NM 88201		
4. Location of Well UNIT LETTER <u>E</u> 1980 FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE. SECTION <u>13</u> TOWNSHIP <u>16S</u> RANGE <u>31E</u> NMPM		

5. Elevation(Show whether DF,RT,GR,etc.) 4404' KB
--

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6-25-83 Set CIBP @ 3100', dumped 200' cmt on top. Cut off @ 2325', broke circ, circ w/200 BFW.
6-26-83 Load hole w/mud. Spot 35sx plug @ csg stub 2325'.
6-28-83 Tagged plug @ 2225', pulled tbg to 1375', set 35sx plug. Tagged plug @ 1368', spot 35sx @ 1368'.
6-29-83 Tagged plug @ 1156', spot 50sx cmt 400-300'.
6-30-83 Tag plug @ 259', spot 15sx @ surface w/dry hole marker.

Location cleaned and ready for inspection.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Dan Stobbs TITLE Drilling & Production Manager DATE 7-28-83

APPROVED BY Barry Swick TITLE Geologist DATE 3-14-84
CONDITIONS OF APPROVAL, IF ANY:

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P.O. Box 2088
SANTA FE, NEW MEXICO 87501

JUL 29 1983

O. C. D.
ARTESIA, OFFICE

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.

E-8560

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT
RESERVOIR. USE "APPLICATION FOR PERMIT-" (FORM C-1011 FOR SUCH PROPOSALS.)

. OIL WELL ☐ GAS WELL ☒ OTHER

. Name of Operator
Read & Stevens, Inc.

. Address of Operator
P.O. Box 1518, Roswell, NM 88201

. Location of Well

UNIT LETTER E 1980 FEET FROM THE North LINE AND 660 FEET FROM
THE West LINE. SECTION 13 TOWNSHIP 16S RANGE 31E NMPM

XXXXXXXXXXXXXXXXXXXXXXXXXXXX 5. Elevation (Show whether DF, RT, GR, etc.)
XXXXXXXXXXXXXXXXXXXXXXXXXXXX 4404' KB

7. Unit Agreement Name

8. Farm or Lease Name
Bogle Farms Com.

9. Well No.

2

10. Field and Pool, or Wildcat
Mesa Queen

12. County
Eddy

XXXXXXXXXXXXXXXXXXXX
XXXXXXXXXXXXXXXXXXXX

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☒

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6-25-83 Set CIBP @ 3100', dumped 200' cmt on top. Cut off @ 2325', broke circ, circ w/200 BFW.
6-26-83 Load hole w/mud. Spot 35sx plug @ csg stub 2325'.
6-28-83 Tagged plug @ 2225', pulled tbg to 1375', set 35sx plug. Tagged plug @ 1368', spot 35sx @ 1368'.
6-29-83 Tagged plug @ 1156', spot 50sx cmt 400-300'.
6-30-83 Tag plug @ 259', spot 15sx @ surface w/dry hole marker.

Location cleaned and ready for inspection.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Bru Stobbs TITLE Drilling & Production Manager DATE 7-28-83

APPROVED BY Baumgardner TITLE Geologist DATE 3-14-84
CONDITIONS OF APPROVAL, IF ANY:

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P.O. Box 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

JUL 29 1983

O. C. D.
ARTESIA, OFFICE

5a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.

E-8560

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT
RESERVOIR. USE "APPLICATION FOR PERMIT-" (FORM C-1011 FOR SUCH PROPOSALS.)

. OIL WELL ☐ GAS WELL ☒ OTHER

. Name of Operator
Read & Stevens, Inc.

. Address of Operator
P.O. Box 1518, Roswell, NM 88201

. Location of Well

UNIT LETTER E 1980 FEET FROM THE North LINE AND 660 FEET FROM
THE West LINE. SECTION 13 TOWNSHIP 16S RANGE 31E NMPM

XXXXXXXXXXXXXXXXXXXXXXXXXXXX 5. Elevation(Show whether DF,RT,GR,etc.)
XXXXXXXXXXXXXXXXXXXXXXXXXXXX 4404' KB

7. Unit Agreement Name

8. Farm or Lease Name
Bogle Farms Com.

9. Well No.

2

10. Field and Pool, or Wildcat
Mesa Queen

12. County
Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☒

Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6-25-83 Set CIBP @ 3100', dumped 200' cmt on top. Cut off @ 2325', broke circ, circ w/200 BFW.
6-26-83 Load hole w/mud. Spot 35sx plug @ csg stub 2325'.
6-28-83 Tagged plug @ 2225', pulled tbg to 1375', set 35sx plug. Tagged plug @ 1368', spot 35sx @ 1368'.
6-29-83 Tagged plug @ 1156', spot 50sx cmt 400-300'.
6-30-83 Tag plug @ 259', spot 15sx @ surface w/dry hole marker.

Location cleaned and ready for inspection.

hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Bruce Stobbs

TITLE Drilling & Production Manager

DATE 7-28-83

APPROVED BY Randy Brooks

TITLE Geologist

DATE 3-14-84

CONDITIONS OF APPROVAL, IF ANY:

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P.O. Box 2088
SANTA FE, NEW MEXICO 87501

JUL 29 1983

O. C. D.
ARTESIA, OFFICE

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.
E-8560

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT
RESERVOIR. USE "APPLICATION FOR PERMIT-" (FORM C-1011 FOR SUCH PROPOSALS.)

. OIL ☐ GAS ☐
WELL ☐ WELL ☒ OTHER

. Name of Operator
Read & Stevens, Inc.

. Address of Operator
P.O. Box 1518, Roswell, NM 88201

. Location of Well

UNIT LETTER E . 1980 FEET FROM THE North LINE AND 660 FEET FROM
THE West LINE. SECTION 13 TOWNSHIP 16S RANGE 31E NMPM

XXXXXXXXXXXXXXXXXXXXXXXXXXXX 5. Elevation (Show whether DF, RT, GR, etc.)
XXXXXXXXXXXXXXXXXXXXXXXXXXXX 4404' KB

7. Unit Agreement Name

8. Farm or Lease Name
Bogle Farms Com.

9. Well No.

2

10. Field and Pool, or Wildcat
Mesa Queen

12. County
Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☒

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6-25-83 Set CIBP @ 3100', dumped 200' cmt on top. Cut off @ 2325', broke circ, circ w/200 BFW.
6-26-83 Load hole w/mud. Spot 35sx plug @ csg stub 2325'.
6-28-83 Tagged plug @ 2225', pulled tbg to 1375', set 35sx plug. Tagged plug @ 1368', spot 35sx @ 1368'.
6-29-83 Tagged plug @ 1156', spot 50sx cmt 400-300'.
6-30-83 Tag plug @ 259', spot 15sx @ surface w/dry hole marker.

Location cleaned and ready for inspection.

hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Bruce Stobbs

TITLE Drilling & Production Manager

DATE 7-28-83

APPROVED BY Randy Brooks
CONDITIONS OF APPROVAL, IF ANY:

TITLE Geologist

DATE 3-14-84

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P.O. Box 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S	
LAND OFFICE	
OPERATOR	

JUL 29 1983

O. C. D.
ARTESIA, OFFICE

5a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.
E-8560

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT-" (FORM C-1011 FOR SUCH PROPOSALS.)

. OIL WELL ☐ GAS WELL ☒ OTHER

. Name of Operator
Read & Stevens, Inc.

. Address of Operator
P.O. Box 1518, Roswell, NM 88201

. Location of Well
UNIT LETTER E 1980 FEET FROM THE North LINE AND 660 FEET FROM
THE West LINE. SECTION 13 TOWNSHIP 16S RANGE 31E NMPM

5. Elevation (Show whether DF, RT, GR, etc.)
4404' KB

XXXXXXXXXXXXXXXXXXXXXXXXXXXX
XXXXXXXXXXXXXXXXXXXXXXXXXXXX
XXXXXXXXXXXXXXXXXXXXXXXXXXXX

7. Unit Agreement Name
-

8. Farm or Lease Name
Bogle Farms Com.

9. Well No.
2

10. Field and Pool, or Wildcat
Mesa Queen

XXXXXXXXXXXXXXXXXXXXXXXXXXXX
XXXXXXXXXXXXXXXXXXXXXXXXXXXX

12. County
Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6-25-83 Set CIBP @ 3100', dumped 200' cmt on top. Cut off @ 2325', broke circ, circ w/200 BFW.
6-26-83 Load hole w/mud. Spot 35sx plug @ csg stub 2325'.
6-28-83 Tagged plug @ 2225', pulled tbg to 1375', set 35sx plug. Tagged plug @ 1368', spot 35sx @ 1368'.
6-29-83 Tagged plug @ 1156', spot 50sx cmt 400-300'.
6-30-83 Tag plug @ 259', spot 15sx @ surface w/dry hole marker.

Location cleaned and ready for inspection.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Bruce Stobbs TITLE Drilling & Production Manager DATE 7-28-83

APPROVED BY Larry Brooks TITLE Geologist DATE 3-14-84
CONDITIONS OF APPROVAL, IF ANY: