

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	✓
FILE	✓
U.S.G.S	
LAND OFFICE	
OPERATOR	✓

5a. Indicate Type of Lease  
State ☒ Fee ☐

5. State Oil & Gas Lease No.

E-8560

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT-" (FORM C-1011 FOR SUCH PROPOSALS.)

• OIL WELL ☐ GAS WELL ☒ OTHER ☐

7. Unit Agreement Name

• Name of Operator  
Read & Stevens, Inc.

8. Farm or Lease Name	Bogle Farms Com.
-----------------------	------------------

• Address of Operator  
P.O. Box 1518, Roswell, NM 88201

9. Well No. 2

UNIT LETTER E, 1980 FEET FROM THE North LINE AND 660 FEET FROM THE West LINE. SECTION 13 TOWNSHIP 16S RANGE 31E NMPM

10. Field and Pool, or Wildcat  
Mesa Queen

XXXXXXXXXXXXXXXXXXXXXXXXXXXX	5. Elevation(Show whether DF,RT,GR,etc.)
XXXXXXXXXXXXXXXXXXXXXXXXXXXX	4404' KB

12. County	XXXXXXXXXXXXXXXXXXXX
Eddy	XXXXXXXXXXXXXXXXXXXX

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	<input type="checkbox"/> SUBSEQUENT REPORT OF
-------------------------	---

PERFORM REMEDIAL WORK	<input type="checkbox"/>	PLUG AND ABANDON	<input type="checkbox"/>
TEMPORARILY ABANDON	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>		<input type="checkbox"/>
OTHER _____	<input type="checkbox"/>		<input type="checkbox"/>

REMEDIAL WORK	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
COMMENCE DRILLING OPNS.	<input type="checkbox"/>	PLUG AND ABANDONMENT	<input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB	<input type="checkbox"/>		<input type="checkbox"/>
OTHER	<input type="checkbox"/>		<input type="checkbox"/>

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6-25-83 Set CIBP @ 3100', dumped 200' cmt on top. Cut off @ 2325', broke circ, circ w/200 BFW.

6-26-83 Load hole w/mud. Spot 35sx plug @ csg stub 2325'.

6-28-83 Tagged plug @ 2225', pulled tbg to 1375', set 35sx plug. Tagged plug @ 1368', spot 35sx @ 1368'.

6-29-83 Tagged plug @ 1156', spot 50sx cmt 400-300'.

6-30-83 Tag plug @ 259', spot 15sx @ surface w/dry hole marker.

Location cleaned and ready for inspection.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Don Hobbs TITLE Drilling & Production Manager DATE 7-28-83

APPROVED BY Randy Brooks TITLE Ecologist DATE 3-14-89  
CONDITIONS OF APPROVAL, IF ANY:

CONDITIONS OF APPROVAL, IF ANY:

Post ID-2  
3-23-84  
P4A