

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN
(Other instructions on reverse side)

PLICATE*

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-029424

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Henshaw Deep Unit

8. FARM OR LEASE NAME

Henshaw Deep Unit

9. WELL NO.

14

10. FIELD AND POOL, OR WILDCAT

Henshaw Wolfcamp

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 24, T-16-S, R-30-E

12. COUNTY OR PARISH

El Paso

13. STATE

New Mexico

1.

OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR

Shell Oil Company (Western Division)

3. ADDRESS OF OPERATOR

P. O. Box 1509, Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below.)

At surface 660' FSL & 660' FWL (SW/4 SW/4)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3837' DF

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETION

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

Re-perforate

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion or Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Pull Wolfcamp production equipment.
2. Perforate with 1/8" JS @ 8704', 8693', 8688', 8686', 8684', 8682' (total 6 holes).
3. Run Easy Drill type BP on wire line & set @ 8750'.
4. Run FBRC to 8600 ±, & spot acid in tubing.
5. Set FBRC & treat with 2000 gals. 15% NE acid in 10-200 gal. stages using ball sealers.
6. Flush with lease crude.
7. Swab.
8. Run production equipment and place on production.

RECEIVED

DEC 21 1967

RECEIVED
DEC 22 1967
U. S. GEOLOGICAL SURVEY
MIDLAND, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

Original Signed By

SIGNED N. W. Harrison N. W. HarrisonTITLE Staff Exploitation EngineerDATE December 21, 1967

(This space for Federal or State office use)

APPROVED BY John A. Brown
CONDITIONS OF APPROVAL, IF ANY:TITLE DISTRICT ENGINEERDATE DEC 21 1967

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.