

NO. OF COPIES RECEIVED	2
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

JUN 15 1973

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

O. C. C.

SUNDY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- <input type="checkbox"/>		5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
2. Name of Operator Charles B. Read		5. State Oil & Gas Lease No. E-8560
3. Address of Operator P.O. Box 2126, Roswell, New Mexico 88201		7. Unit Agreement Name -
4. Location of Well UNIT LETTER G 1650 FEET FROM THE North LINE AND 1650 FEET FROM THE East LINE, SECTION 14 TOWNSHIP 16S RANGE 31E NMPM.		8. Farm or Lease Name Bogle Farms
		9. Well No. 3
		10. Field and Pool, or Wildcat Mesa Queen
15. Elevation (Show whether DF, RT, GR, etc.) 4402' GL		12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Request Permission to P & A in the following manner:

1. Squeeze perf. 3319-3330' w/35 sx. cmt.
2. Load hole with good gel mud
3. Cut 2 7/8" csg.
4. Set 35 sx. Plug @ csg. stub.
5. Set 35 sx. Plug @ 2330' to 2230'
6. Set 35 sx. Plug @ 1250' to 1150'
7. Set 35 sx. Plug @ 425' to 325'
8. Set 10 sx. Plug @ 10' to 0'
9. Install regulation marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Agent DATE 5/14/73

APPROVED BY [Signature] TITLE OIL AND GAS INSPECTOR DATE JUN 18 1973

CONDITIONS OF APPROVAL, IF ANY: