

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION  
P.O. Box 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>

5. State Oil & Gas Lease No.

OG-1214

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT-" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☐ GAS WELL ☐ OTHER Dry hole

2. Name of Operator  
Read & Stevens, Inc.

3. Address of Operator  
P.O. Box 1518, Roswell, NM 88201

4. Location of Well

UNIT LETTER F, 1650 FEET FROM THE North LINE AND 1650 FEET FROM  
THE West LINE. SECTION 12 TOWNSHIP 16S RANGE 31E NMPM

7. Unit Agreement Name

8. Farm or Lease Name  
Bogle Farms "A"

9. Well No.

4

10. Field and Pool, or Wildcat

West Mesa Hopper Queen Asso.

5. Elevation (Show whether DF, RT, GR, etc.)  
4394.1' GL

12. County  
Eddy

XXXXXXXXXXXXXXXXXXXX  
XXXXXXXXXXXXXXXXXXXX

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐  
OTHER ☐

PLUG AND ABANDON ☐  
CHANGE PLANS ☐

REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER ☐

ALTERING CASING ☐  
PLUG AND ABANDONMENT ☒

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-23-84 Trip out w/tbg, set CIBP @ 3248', dumped 35' cmt on top of plug, circ hole w/salt gel mud.

5-24-84 Cut csg @ 2095', stuck, cut @ 1836', would not come loose, cut @ 1826', stuck, cut @ 1200', pulled 1200' of 4 1/2" csg, ran tbg to 335', surface csg collapsed, washed to 875', SDON.

5-25-84 Plug tagged @ 1147'. Spotted plugs @ 2216'-2316' 7sx Class "C" cmt  
1800'-1875' 5.2sx Class "C" cmt  
1150'-1350' 26sx Class "C" cmt  
389'-290' 23sx Class "C" cmt

5-26-84 Tagged plug @ 293', cut off, set 25sx surface plug @ 30', cut off deadmen and install dry hole marker.

Post ID-2  
6-8-84  
Comp & BR  
PFA

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Bruce Stobbs

TITLE Drilling & Production Manager

DATE 5-29-84

APPROVED BY Randy Brooks

TITLE Geologist

DATE 6-24-85

CONDITIONS OF APPROVAL, IF ANY: