STATE OF NEW	MEXICO	, and					
ENERGY AND MINERAL	S DEPARTMENT			-	3	5 . 0 . 107	
NO. OF COPIES REC	EIVED	OIL CONSE	RVAT LON	DIVIS PRECEIVED BY	1	Form C-103	
DISTRIBUTION		P.0	. Box 2	CB8		Revised 10-1-78	
SANTA FE	V	SANTA FE.	NEW ME.	x co 821AN 26 1984	5a Indicate	Type of Lease	
FILE	W.	•					
U.S.G.S				O. C. D.	State X	Fee	
LAND OFFICE				ARTESIA, OFFICE	5 State 011	& Gas Lease No.	
OPERATOR	V				J. State Off	a Gas Lease No.	
					oc-	6016	
SUNDRY NOTICES AND REPORTS ON WELLS						XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT						XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	
RESERVOIR. USE "APPLICATION FOR PERMIT-" (FORM C-1011 FOR SUCH PROPOSALS.)						XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	
1. OIL GAS						7. Unit Agreement Name	
WELL	WELL X	OTHER			1	ett Namo	
2. Name of Operator						N.	
Read & Stevens, Inc.						8. Farm or Lease Name Bogle Flats	
3. Address of Operator					9. Well No.		
P.O. Box 1518, Roswell, NM 88201					3. nes 1 no.		
4. Location of Well					10. Field and Pool, or Wildcat		
UNIT LETTER N . 990 FEET FROM THE South LINE AND 1650 FEET FROM					Mesa Queen		
THE West L	INE. SECTION_	12 TOWNSHIP	16\$	RANGE 31E NMPM		××××××××××××××××××××××××××××××××××××××	
XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	ľ	5. Elevation(Show w	hether [OF,RT,GR,etc.)	12. County	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	
XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXX	43931 GL			Eddy	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	
Check Appropriate Box To Indicate Nature of Notice, Report or Othe						1	
NOTICE OF INTENTION TO: SUBSEQUENT REL					EPORT OF:		
PERFORM REMEDIAL	L WORK	PLUG AND ABANDON	丁	REMEDIAL WORK	ALTERIA	NG CASING	
TEMPORARILY ABAN	NDON	OHANGE PLANS		COMMENCE DRILLING OPNS.		ND ABANDONMENT X	
PULL OR ALTER CA	ASING	<u> </u>		CASING TEST AND CEMENT JOB	1200 %	AD YOUADOUMENT X	
OTHER	,			OTHER			
Describe Proposed o	or Completed O	perations(Clearly sta	ate all	pertinent details, and give	e pertinent date	es. Including esti-	
mated date of start	ting any propos	sed work) SEE RULE 1	103.	,	,	er, the tacking of the	
1-6-84	Set CIBP @	3150' w/35' cmt, cut	e 1800), Load hole w/mud, pipe s	tuck.		
1-7-84	Spot 48sx o	cmt 1800'-1050'					
1-9-84 Tagged @ 1024', cut @ 1050', circ hole, could not pull csg, cut @ 350', trlp out w/ 4							
		31H to 1050', spot 35	sx plug	1050'-950', spot 35sx plug	g @ 350', tag @	3051,	
	surface plu	3					
i hereby certify t	hat the inform	mation above is true	and com	plete to the best of my kno	wledge and beli	ef.	
//	•	QL 11					
SIGNED	21-/6	ribly I	ITLE D	rilling & Production Manage	or DATE	1-25-84	
	7)						
APPROVED BY	Danish	LOOK T	ITLE	Hoston	DATE	3-14-84	
CONDITIONS OF AP	PROVAL, IF ANY			The way to	DAIL_		

7057,3 Pak