


NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE	1	
FILE	1	✓
U.S.G.S.		
LAND OFFICE		
OPERATOR	1	



Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	E 8560

**BLM 1**

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator Remuda Operating Company ✓	8. Farm or Lease Name Southern Union
3. Address of Operator 150 Mid America Bldg. Midland, TX 79701	9. Well No. 1 <i>st com</i>
4. Location of Well UNIT LETTER <u>J</u> <u>2310</u> FEET FROM THE <u>South</u> LINE AND <u>2310</u> FEET FROM THE <u>East</u> LINE, SECTION <u>13</u> TOWNSHIP <u>16S</u> RANGE <u>31E</u> NMPM.	10. Field and Pool, or Wildcat Mesa Queen
15. Elevation (Show whether DF, RT, GR, etc.) <i>4387' G 15</i>	12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spot 20 sx plug @ 3430 & tag; pull 4 1/2" casing and spot 35 sx plug @ cutoff + tag point. Spot 100' plug @ 2150'-2250', 100' plug @ 1200'-1300. 50 sx plug @ 8 5/8 set @ 433', 10 sx plug @ top.  
mud between all plugs  
Install marker & clean up location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Neil Fisher TITLE AGENT DATE 10/11/85

APPROVED BY Mike Williams TITLE OIL AND GAS INSPECTOR DATE OCT 17 1985

CONDITIONS OF APPROVAL, IF ANY: Notify N.M.O.C.C. in sufficient time to witness