

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN (Other instructions on reverse side) LOCATE*

Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

LC 069465

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Dry Hole		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR Shall Oil Company (Western Division)		8. FARM OR LEASE NAME Stablein Federal	
3. ADDRESS OF OPERATOR P. O. Box 1509, Midland, Texas 79701		9. WELL NO. 1	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1980' FNL & 660' FEL, Section 10, T-16-S, R-30-E NMPM Survey, Eddy County, New Mexico		10. FIELD AND POOL, OR WILDCAT Henshaw Area Wildcat	
14. PERMIT NO. -		15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3865' DF	
		12. COUNTY OR PARISH Eddy	
		13. STATE New Mexico	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recombination Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

August 13, 1967 thru September 19, 1967

1. Spotted following cement plugs:

- A. 50 sacks at 9150'
- B. 25 sacks at 7800'
- C. 25 sacks at 6500'
- D. 25 sacks at 5000'
- E. 50 sacks at 3150'

2. Determined free point shot and pulled 8 5/8" casing at 1901'.

3. Ran 2" tubing to 1950'.

4. Spotted 50 sacks cement plug.

5. Pulled tubing to base of 11 3/4" casing at 550', spotted 50 sacks cement plug.

6. Pulled tubing.

7. Spotted 10 sacks plug at surface.

8. Erected prescribed marker. Well P&A 9-19-67.

RECEIVED
OCT 12 1967
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

OCT 11 1967

U. S. GEOLOGICAL SURVEY
ROSWEIL, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED D. L. Lilly TITLE Division Mechanical Engineer DATE October 10, 1967

(This space for Federal or State office use)

APPROVED BY
SIGNATURES OF APPROVAL, IF ANY:

TITLE _____ DATE _____

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.