

COUNTY OF NEW MEXICO
 DISTRICT OF 1
 NAME OF WELL 14-17 N-80+1-55
 OPERATOR AMERICAN PETROLEUM CORPORATION
 LAND OFFICE AMERICAN PETROLEUM CORPORATION
 OPERATOR AMERICAN PETROLEUM CORPORATION

RECEIVED

NEW MEXICO OIL CONSERVATION COMMISSION

JAN 2 1969

**O. C. C.
ALBUQUERQUE, OFFICE**

Form O-107
 Supersedes Old
 O-107 and O-108
 Effective 1-1-66

SLDRY NOTICES AND REPORTS ON WELLS
DO NOT USE THIS FORM FOR A WELL WHICH IS TO BE PLUGGED OR PLUG BACK TO A DIFFERENT RESERVOIR.
 USE APPLICATION FOR PLUG BACK FORM O-101 FOR SUCH PLUG BACKS.

1. ☐ WELL ☐ CA. ☐ OTHER DRY HOLE

2. NAME OF WELL AMERICAN PETROLEUM CORPORATION

3. ADDRESS OF OPERATOR BOX 68, MOORE, N. M. 88400

4. LOCATION OF WELL
 UNIT LETTER P 1190 FEET FROM THE SOUTH LINE AND 1090 FEET FROM
 THE EAST LINE, SECTION 30 TOWNSHIP 17-S RANGE 28-E N.M.P.M.

5. Elevation (Show whether DP, RT, Gt, etc.) 3554' R.D.B.

6. ☐ 13. Elevation (Show whether DP, RT, Gt, etc.) 3554' R.D.B.

7. Unit Agreement Name STATE V Gas COIL

8. Name of Lessee STATE V Gas COIL

9. Well No. 14-17 N-80+1-55

10. County EDM

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

REMEDIAL WORK ☐

ALTERING CASING ☐

TEMPORARILY ABANDON ☐

COMMENCE DRILLING OPS. ☐

PLUG AND ABANDONMENT ☐

PULL OR ALTER CASING ☐

CHANGE PLANS ☐

CASING TEST AND CEMENT JOBS ☐

OTHER Completed in attempt ☒

17. Description of Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work, see Rule 1100.)

On 12-20-68, 5 1/2" OD 14-17" N-80+1-55 Casing was
 set @ 10,237' x 350'. Inferred 4 1/2" HIL + 500.24' meat:
 Tested casing w/ 2800 psi for 30 min. Test O.R.
 After HOC app'd 48' HIL, gas reported 9944-47,
 9967-69, 9992-10,000' w/ 255 PF. Acid w/ 1000 gal 15%.
 Evaluation - Pass. Ignored w/ 60% cement. TCM-9355' Gravel
 Lost after 9512-58 w/ 255 PF. Acid 1000 gal more, 2000 gal 15%. Evaluation.
 Dry hole completion 12-31-68. Prepare to P+H as follows: Set 25x4.
 across from 9512-58; Shoot 5 1/2" from 9512-58; 35x4 plug from end
 of steel; 35x4 @ 50' down + above 480-5070, 1500-4810; 35x4-60000;
 35x4-60000; 35x4 from 1004' 1964; 1004' 20000 w/ P+H marks.
 Make from cleanup + restore ground to condition.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W. A. Gressett

TITLE AREA SUPERINTENDENT

DATE JAN 2 1969

OIL AND GAS INSPECTOR
 APPROVED W. A. Gressett
 OFFICE OF APPROVAL, IF ANY:
 1-1-66

TITLE OIL AND GAS INSPECTOR

DATE JAN 2 1969