NO. OF COPIES RECE	IVED	4						=-: '		Form C-103				
DISTRIBUTIO	N I									Supersedes O C-102 and C-1				
SANTA FE			-	NE	MEXICO OF	L GONSE	RVATION CO	MMISSION		Effective 1-1-				
FILE		- 1	7		Mark The A	ا مدا و	-							
U.S.G.S.			_						50	. Indicate Type	of Lease			
LAND OFFICE					NO	V 1 9	1973			State X	Fee	, LJ		
OPERATOR		. ,	\neg						5.	State Oil & Go	ıs Lease No.			
		· · · · ·				سا ال	C			K 3630				
· · · · · · · · · · · · · · · · · · ·		SLIN	JDRY NC	TICES	AND REPOR	HS ONE	WEIDES					/////		
SUNDRY NOTICES AND REPORTS ON THE LES (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.)														
1.									7	. Unit Agreemen	it Name			
OIL WELL	GAS WELL	X	01	THER-										
2. Name of Operator											8. Farm or Lease Name			
Pennzoil Company /											Aid State Com.			
3. Address of Operator										9. Well No.				
P. O. Drawer 1828 - Midland, Texas 79701]			
4. Location of Well									ì	0. Field and Po	ol, or Wildcat			
UNIT LETTER	А		660	FEE	T FROM THEN	orth	LINE AND	660	T FROM	Aid Morr	ow Gas			
5 ATT 52 T T T														
THE East		INE. S	FCT10N	24	TOWNSHIP	17 - S	RANGE	28-E	NMPM.					
											7//////	<i>HH</i>		
	1111	111	11111	15.	Elevation (Show	whether	DF, RT, GR, et	c.)	1	2. County				
		///		M		3727	D.F			Eddy	_7/////	11111		
16.		Che	ck Appr	opriate	Box To Ind	icate N	ature of No	tice, Report (or Other	Data				
			FINTEN							REPORT OF	:			
	ſ۷	1							_	A) TE	RING CASING			
PERFORM REMEDIAL V]]			PLUG AND ABAN	DON	REMEDIAL WOR	F	=-		AND ABANDONME	FNT H		
TEMPORARILY ABANDO	-	1			CHANGE PLANS		COMMENCE DRI	ND CEMENT JOB	=	7200	ARD ABARDONING			
PULL OR ALTER CASIN	IG [J			CHANGE PLANS	ا لــــا	OTHER	_						
							OTRER							
OTHER		_				لـــا								
17. Describe Propos work) SEE RUL		mplet	ed Operatio	ons (Clea	erly state all pert	inent det	ils, and give p	ertinent dates, in	cluding es	timated date of	starting any p	roposed		
,														
11-14-73	Set b	lani	king pl	lug ir	n packer, b	ackof	f packer,	circulate	hole i	with 2%				
	KCI w	ate	r.											
	Retri	eve	blank	ing pl	ug, unseat	t pack	er and pu	11 tubing,	packe	r and				
			ing gur											
	•		•							- 6				
11-15-73	Treat Morrow zone w/3,500 gallons of 7.5% MS acid w/l,000 SCF of													
	No pe	r b	arrel.											
	Flow and swab well in, put on line and test.													
	1 1011	uilu	JHUD (,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	, pac on									

18. I hereby certify at the information above is true and complete to the best of my knowledge and belief.

SIGNED TITLE Petroleum Engineer

DATE 11-16-73

APPROVED BY OF GREAT TOP DATE NOV 1 9 1973