o not use this form for proposals to drill or to de Use "APPLICATION FOR PERMIT- SUBMIT IN TRIPL Type of Well Gas Duher P&A Name of Operator	AUG 0 7 1991 O. C. D. ORTS ON WELLERTESIA, OFFICE epen or reentry to a different reservoir. —" for such proposals	Budget Bureau No. 1004-0135 Expires: March 31, 1993 5. Lease Designation and Serial No. NM0439900 6. If Indian, Allottee or Tribe Name 7. If Unit or CA, Agreement Designation
o not use this form for proposals to drill or to de Use "APPLICATION FOR PERMIT- SUBMIT IN TRIPL Type of Well Gas Duher P&A Name of Operator	ORTS ON WELLARTESIA, OFFICE epen or reentry to a different reservoir. 	
SUBMIT IN TRIPL Type of Well Gas Oil Gas Well Other Name of Operator		7. If Unit or CA, Agreement Designation
Oil Gas P&A Well Other P&A		
Name of Operator		8. Well Name and No. Federal CB #1
ATES PETROLEUM CORPORATION	:	9. API Well No. 30-015-20489
Address and Telephone No. 05 South 4th St., Artesia, NM 88210	(505) 748-1471	10. Field and Pool, or Exploratory Area Eagle Creek S.A.
Location of Well (Footage, Sec., T., R., M., or Survey Description) Unit N. 330'FSL & 2310' FWL,		11. County or Parish, State Eddy, NM
CHECK APPROPRIATE BOX(s) TO INI	DICATE NATURE OF NOTICE, REPC	RT, OR OTHER DATA
TYPE OF SUBMISSION		
Notice of Intent	Abandonment Sugar, Recompletion Advances	Change of Plans Construction New Construction Non-Routine Fracturing
Final Abandonment Notice	Plugging Back Casing Repair Altering Casing	Water Shut-Off
	A Other Plug and abandon.	Dispose Water (Note: Report results of multiple completion on Wel Completion or Recompletion Report and Log form.
. Describe Proposed or Completed Operations (Clearly state all pertinent des give subsurface locations and measured and true vertical depths for	tails, and give pertinent dates, including estimated date of start	ling any proposed work. If well is directionally drill
give subsurface locations and measured and the vertical option of We propose to plug and abandon a	s follows:	
1. 25 sx class "C" 1250'-915'.		
2. 25 sx class "C" 460'-220'.		
3. 10 sx class "C" 75'-surface.		
4. Cut off well head at surface	e. Weld dry hole marker.	
	1	
	·	
		·
14. I hereby certify that the foregoing is true and correct	<u></u>	
single anita Da illette	Tide Production Supervisor	Date 8-6-91
(This space for Federal or State office use)	Title	Detc
Approved by Conditions of approval, if any:		je se

.

į