

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TR. (CATE*)
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

BM 2507

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

TRIG FEDERAL

9. WELL NO.

1-T

10. FIELD AND POOL, OR WILDCAT

WILDCAT11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA**Sec. 7, T-16S, R-31E**

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3930' Gr.

12. COUNTY OR PARISH

Elddy

13. STATE

New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other) **Spud**(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spudded 15" hole at 10:30 AM 12/7/71. Drilled 15" hole to 525' & set 11 3/4" OD 420 J-35 SUEC Casing at 540' & cemented to surface w/ 350 Sx. cement. Plug down 3:00 AM 12/8/71. WOC 10 hrs. & tested with 1000# for 30 Mins.; Held OK. Drilled 11" hole to 3202'.
12/13/71 Set 32 Jts. 320 Super K-55 & 78 Jts. Super K-55 240 @ 3202' w/ 300 Sx. Class "C" w/ 140 salt/Sx. & 380 Sx. Class "C" w/ 2% CaCl; P.D. 3:43 AM 12/15/71. No water back flow out of annulus; will run bond log.
12/16/71 T.D. 3202'; Cut off & cut slips; tested Csg. 1000 psi 30 Mins; held OK; Run cement bond log; top cement 825'. 825-1350' some cement, poor bond; 1350-1425' very little bond; 1425-1890' poor bond (over 50%); 1890-2070' less than 50% bond; 2070-2270' over 80% bond; 2270-2500' 100% bond; 2500-2750' 50 - 70% bond; 2750-2885' 70% bond; 2885-3000' over 50% poor bond; 3000-3108' 80 - 90% bond; 3108-3112' no bond; Could not get below 3112'; picked up drill pipe & went to Float Collar @ 3170'; drilling on float collar & plan to drill out & re-run Bond Log below 3112'; have casing water flow.

18. I hereby certify that the foregoing is true and correct

SIGNED

E. M. Schell

TITLE

District Engineer

DATE

1/12/72

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side

RECEIVED
JAN 14 1972
U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO**APPROVED**
JAN 14 1972
R. L. BECKWITH
ACTING DISTRICT ENGINEER

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.