Form 9-331 (May 1963)

UNITED STATES SUBMIT IN TRIPLICATE* DEPARTMENT OF THE INTERIOR (Other instructions on reverse side)

Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.

)
	C/SF GEOLOGICAL SURVEY	NM 14483
	SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
1.	OIL GAS WELL OTHER OIL OF SUCH PROPOSAIS, OIL OF SUCH PROPOSAIS, OIL CONS. COMMISSION NAME OF OPERATOR	7. UNIT AGREEMENT NAME
2.	NAME OF OPERATOR	8. FARM OR LEASE NAME
	McCLELLAN OIL CORP.	June Fed. Com.
3.	ADDRESS OF OPERATOR	9. WELL NO.
	Post Office Drawer 730 Roswell, N. M. 88202/ED	1
4.	LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)	10. FIELD AND POOL, OR WILDCAT
	At surface	High-Nitro Premier
	NOV 1 2 1981	11. SEC., T., R., M., OR BLK. AND SURVEY OR ABEA
	660' FSL, 1980' FEL	
	O. C. D.	Sec. 4 T16-S R29-E
14.	PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, CR, etcARTESIA, OFFICE	12. COUNTY OR PARISH 13. STATE
	3699' GL	Eddy N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:				SUBSEQUENT REPORT OF:		
TEST WATER SHUT-OFF		PULL OR ALTER CASING MULTIPLE COMPLETE		WATER SHUT-OFF FRACTURE TREATMENT	REPAIRING WELL ALTERING CASING	
SHOOT OR ACIDIZE		ABANDON*	<u> </u>	SHOOTING OR ACIDIZING	ABANDONMENT*	
REPAIR WELL		CHANGE PLANS		(Other)		
(Other)				(NOTE: Report results of mu Completion or Recompletion 1	Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *


Propose to plug and abandoned this hole as follows:

Pull Tubing, Pull $5-\frac{1}{2}$ " casing @ free point. Set cement plug from 2250'-2350' across present perforations.

100' cement plug in and out of stub of $5-\frac{1}{2}$ " casing. 100' cement plug from 320-420' in and out of 8-5/8" casing.

15 SX plug at surface.

Place dry hole marker and restore surface to original condition.



OIL & GAS U.S. GEOLOGICAL SURVEY ROSWELL, NEW MEXICO

8. I hereby certify t	hat the foregoing is true and correct		
signed Ma	ah mschollam	TITLE Geologist	DATE 11/2/81
	rederal or State office use)		
(0	rig. Sgd.) PETER W. CHESTER		
APPROVED BY	APPROVAL, IF A NY 40 C1	TITLE	DATE
	CONDITIONS OF APPROVADOF1 OX 1981		
	FOR		
	JAMES A. GILLHAM +C)	
	JAMES A. GILLHAM DISTRICT SUPERVISOR*Se	le Instructions on Keverse Dide	