

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	5. LEASE DESIGNATION AND SERIAL NO. <i>M-1135-C</i>
2. NAME OF OPERATOR <i>Dalport Oil Corporation</i>	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR <i>3471 First National Bank Bldg. Dallas, TX 75202</i>	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface <i>660' to 1980' FWL Sec. 11, T-16-S R-28-E</i>	8. FARM OR LEASE NAME <i>Edman Fed.</i>
14. PERMIT NO.	9. WELL NO. <i>1</i>
15. ELEVATIONS (Show whether DF, RT, GR, etc.) <i>Unknown</i>	10. FIELD AND POOL, OR WILDCAT <i>Wildcat</i>
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <i>11-T-16S, R-28-E</i>
	12. COUNTY OR PARISH <i>Lea County</i>
	13. STATE <i>NM</i>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Data:

8-5/8" Surface Csg Set @ 330' : Circulated w/ cmt.
4-1/2" Production Csg Set @ 1865' w/ 275 Sx Cmt.
Perfs. @ 1821-1827

1-30-75

Plugged and abandoned as follows:

1. Set CIBF @ 1750' : dumped 35' Cmt on plug.
2. Shot 4 1/2" Csg @ 1171' : Shot & recovered from 1010'
3. Set 45 sk cmt plug from 1010' to 953'
4. Set cmt plug from 441' to 320'
5. Set 10 sk cmt plug @ surface : installed dry hole marker

Note:

Hole was circulated w/ salt water brine gelled mud
and all plugs pumped w/ salt water mud

18. I hereby certify that the foregoing is true and correct

SIGNED _____ TITLE *Agent* DATE *2-9-75*

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

RECEIVED

MAR 16 1976

O. C. C.
ARTESIA, OFFICE

RECEIVED

FEB 12 1975

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well, and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.