

DEVELOPMENT PLAN FOR SURFACE USE
(Continued)

11. Plans for restoration of the surface.

Location will be leveled and cleaned with all pits filled.

12. General description of the topography, vegetation, and other aspects of the area.

The general area is characterized as an arid desert area with little or no vegetation.

13. The field representative in charge of operations will be Mr. W. H. Cravey,
Phone No. 505-393-5905, Hobbs, New Mexico.