ND. OF COPIES AECEIVED	DEC ED	Form C~103
DISTRIBUTION		Supersedes Old C-102 and C-103
SANTA FE V NEW ME	EXICO OIL CONSERVATION COMMISSION	
FILE	exico oil conservation commission MAR 1.7 1983	
U.S.G.S.		Sa. Indicate Type of Lease
LAND OFFICE	O. C. D.	State Fee X
OPERATOR	ARTESIA, OFFICE	5. State Oil 6 Gas Lease No.
SUNDRY NOTICES AND 100 NOT USE THIS FORM FOR PROPOSALS TO DRILL OF T USE "APPLICATION FOR PERMIT -" F	O DEEPEN OR PLUS BACK TO A DIFFERENT RESERVOID.	
[].		7. Unit Agreement Name
OIL GAS WELL OTHER-		
2. Name of Operator	· · · · · · · · · · · · · · · · · · ·	9. Farm or Lease Linne
Hanson Operating Company, Inc.		Big Buck Pounds
3. Address of Operator		9. Well No.
P. O. Box 1515, Roswell, New Mexic	88202-1515	#1
4. Location of Well		10. Field and Pool, or Wildcat
	South 660	
UNIT LETTER I 1980 FEET FROM	A THE DULLII LINE AND 000 FE	ET FROM
THE East LINE, SECTION 27	TOWNSHIP 17S RANGE 26E	ныры. (() () () () () () () () () () () () ()
	ition (Show whether DF, RT, GR, etc.)	12. County
	24' GL 3336 KB	
ÖTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTT	24 GL 3330 KB	Eddy
^{15.} Check Appropriate Box	To Indicate Nature of Notice, Report	or Other Data
NOTICE OF INTENTION TO:	SUBSE	QUENT REPORT OF:
		· · · · ·
PERFORM REMEDIAL WORK	S AND ABANDON X REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPHS.	PLUG AND ABANDONMENT
PULL OF ALTER CASING	NGE PLANS CASING TEST AND CEMENT JOB	
	οτμε <u>ρ</u>	Γ
0TH = 7		
-		
17. Describe Proposed or Completed Operations (Clearly str work) SEE RULE 1103.	ite all pertinent details, and give pertinent dates, i	ncluding estimated date of starting any propose
Production from this well has dec The following casing strings were		ger economical to produce.
•		
12-3/4" @500' - 300 sx cemen		
8-5/8" @1455' - 485 sx ceme		
5-1/2" @8821' TD - 300 sx,	top of cement 7800'	
Pursuant to telephone conversation (Hanson Operating Company, Inc.), 30 sack plug across perfs 8	we plan to plug and abandon the	
30 sack plug top Cisco form	-	
100 sack plug at 5-1/2" stub		
100 sack plug at 2500'		
100 sack plug at 2500' 50 sack plug in and out 8-5	/8" at 1455'	· · · · · · · · · · · · · · · · · · ·
50 sack plug in and out $8-5$		an a
50 sack plug in and out 8-5 10 sack plug and marker at		
50 sack plug in and out 8-5 10 sack plug and marker at	surface	gel mud, estimated 25 sacks.
50 sack plug in and out 8-5 <u>10</u> sack plug and marker at 320 sacks Before spotting plugs, well will	surface	gel mud, estimated 25 sacks.
50 sack plug in and out 8-5 10 sack plug and marker at 320 sacks	surface	gel mud, estimated 25 sacks.
50 sack plug in and out 8-5 <u>10</u> sack plug and marker at 320 sacks Before spotting plugs, well will	surface be circulated with fresh water ; complete to the best of my knowledge and belief.	
50 sack plug in and out 8-5 <u>10</u> sack plug and marker at 320 sacks Before spotting plugs, well will	surface be circulated with fresh water ; complete to the best of my knowledge and belief.	
50 sack plug in and out 8-5 <u>10</u> sack plug and marker at 320 sacks Before spotting plugs, well will	be circulated with fresh water production Analyst	gel mud, estimated 25 sacks.
50 sack plug in and out 8-5 <u>10</u> sack plug and marker at 320 sacks Before spotting plugs, well will	be circulated with fresh water p pemplete to the best of my knowledge and belief. TITLE Production Analyst Original disorder by Leslie A. Cloneads	DATE03/15/83
50 sack plug in and out 8-5 <u>10</u> sack plug and marker at 320 sacks Before spotting plugs, well will	be circulated with fresh water production Analyst	