

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

NM OIL CONS. COMMISSION
Drawer DD
Artesia, NM 88210

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

5. Lease Designation and Serial No.
NM-0439900A

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Federal CR #2

9. API Well No.

10. Field and Pool, or Exploratory Area

Eagle Creek San Andres

11. County or Parish, State

Eddy County, New Mexico

1. Type of Well
☐ Oil Well ☐ Gas Well ☒ Other P & A Well

2. Name of Operator

YATES PETROLEUM CORPORATION (505) 748-1471

3. Address and Telephone No.

105 South 4th St., Artesia, NM 88210

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

330' FSL & 990' FWL of Section 29-T17S-R25E

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Plugged and abandoned well as follows:

Moved in and rigged up pulling unit. Nippled down wellhead and nippled up 6" BOP. GIH w/3-11/16" gauge ring on 2-3/8" tubing to 1115'. POOH. TIH w/4-1/2" tubing. Set CIBP at 1100'. Circulated hole with 10# mud. Spotted 10 sacks cement from 1100-1050'. POOH. Dug out wellhead. 7" casing was welded to 5-1/2" casing. TIH and perforated 2 jet shots at 75'. Calculated free point at 200'. TIH w/tubing to 1050'. Spotted 15 sacks cement. POOH. WOC. TIH and tagged cement at 850'. POOH. TIH and perforated casing at 636'. Set 5-1/2" packer at 560'. Did not have returns out of 7" casing. POOH with packer. TIH with cement retainer and set at 560'. Squeezed 65 sacks Class "C" 2% CaCl2. Spotted 30 sacks cement on top of retainer. POOH. Pumped down 5-1/2" casing from surface. Circulated cement outside 7" with 20 sacks. Cut off wellhead and installed regulation abandonment marker. PLUGGED AND ABANDONED - FINAL REPORT.

Plugging completed on July 30, 1993.

Approved by the Bureau of the well bore.
Landing and cementing completed until
surface was reached and cemented.

Part ID-2
10-15-93
P & A

14. I hereby certify that the foregoing is true and correct

Signed Rusty Kline

Title Production Clerk

Date Sept. 3, 1993

(This space for Federal or State office use)

Approved by (ORIG. SGD.) JOE G. LARA

Title PETROLEUM ENGINEER

Date 10/6/93

Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

*See Instruction on Reverse Side